

ANNUAL SURVEYS.

42280

(Received at London Office, 24 Feb 83)

No. 17 Survey held at London Date, first Survey 6 Feb Last Survey 22 Feb 1883
 Reg. Book. 17 Supp on the Iron S.S. "Mosses" Master Longley (No. of Visits 2)
 Tonnage { Net 1323 Built at Stockton When built 1882 5
 Gross 2035 By whom built Richardson Owners Shaw, Bushby & Co
 Under Dk. 1939 Port belonging to London Destined Voyage China & Japan
 If Surveyed Afloat or in Dry Dock Linckhild Dry Dk (State Name of Dock.)

Last Survey, No. 4921 Port of Ltd Classed 100 A1
 Years assigned 6-82 Character in Register Book.

Present Condition of the Decks good Treenails None good
 Waterways --- Breasthooks and Stemson not seen
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings not seen Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes good Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder good
 Plank (Bottom) and Counter --- Copper or Y.M. Cement When put on 1882
 Engine Room Skylights good Caulking of Bottom, Deck, & Waterways good
 Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good
 Hatches good

Windlass and Capstan good
 Pumps 4 no good
 Boats 4 no good
 Masts, Yards, &c. good
 Condition, how ascertained from Deck
 Sails good
 Anchors, No. of 3 B-1 S-2 K
 Cables not seen
 Hawasers and Warps 6 no good
 Standing and Running Rigging good

General Observations, Opinion as to Class, &c.
Bottom cleaned, examined and painted
She is now in good condition and eligible to remain as classed.

Committee's Minute Friday, 2nd March, 1883.
 Character assigned 100 A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 17 Survey held at London Date, first Survey 6 Feb Last Survey 22 Feb 1883
 Reg. Book. 17 Supp on the Iron S.S. "Mosses" Master Longley (No. of Visits 2)
 Tonnage { Net 1323 Built at Stockton When built 1882 5
 Gross 2035 By whom built Richardson Owners Shaw, Bushby & Co
 Under Dk. 1939 Port belonging to London Destined Voyage China & Japan
 If Surveyed Afloat or in Dry Dock Linckhild Dry Dk (State Name of Dock.)

Last Survey, No. 4921 Port of Ltd Classed 100 A1
 Years assigned 6-82 Character in Register Book.

Present Condition of the Decks --- Treenails ---
 Waterways --- Breasthooks and Stemson ---
 Comings --- Transoms, Pointers, and Crutches ---
 Upper Deck Beams & Fastenings --- Timbers of the Frame at the Openings ---
 Lower Deck Beams & Fastenings --- Ditto ditto at other places ---
 Planksheers --- Keelsons ---
 Sheerstrakes --- Clamps and Shelves ---
 Topsides --- Ceiling ---
 Wales --- Rudder ---
 Plank (Bottom) and Counter --- Copper or Y.M. When put on ---
 Engine Room Skylights --- Caulking of Bottom, Deck, & Waterways ---
 Coal Bunkers, Openings, Lids, &c. --- Scuppers --- Cargo and Main Hatchways ---
 Hatches ---

Committee's Minute 18
 Character assigned ---
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



Use or of space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

1890-699207