

ANNUAL SURVEYS.

442300

No. 281 Survey held at London Date, first Survey 1st Feb Last Survey 27th Feb 1883
 No. in on the SS Drummond Castle Master R Jones
 Reg. Book. 407 Net 2381 Built at Glasgow When built 1881 Year. 2 Month.
 Tonnage { Gross 3705 By whom built J Elder & Co Owners J Currie & Co
 Under Dk. 3537 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens St & afloat
 (State Name of Dock.)

Last Survey, No. 11076 Port of Lyon

Classed 100A1 Years assigned. 11.82 Character in Register Book.

Present Condition of the

Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	
Planksheers <u>"</u>	Keelsons <u>"</u>	
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	
Topsides <u>"</u>	Ceiling <u>"</u>	
Wales <u>"</u>	Rudder <u>"</u>	
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Couted</u> When put on <u>Now</u>	
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	
Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>	
General Observations, Opinion as to Class, &c. <u>Bottom &c. coated, and eligible to remain as classed.</u>		

Committee's Minute Friday, 27 March, 1883.

Character assigned 100A1

Senhouse Martindele

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Net Built at When built Year. Month.
 Tonnage { Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of

Classed Years assigned. Character in Register Book.

Present Condition of the

Decks <u> </u>	Treenails <u> </u>	<u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	
Planksheers <u> </u>	Keelsons <u> </u>	
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	
Topsides <u> </u>	Ceiling <u> </u>	
Wales <u> </u>	Rudder <u> </u>	
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	
Cargo and Main Hatchways <u> </u>	Hatches <u> </u>	
General Observations, Opinion as to Class, &c. <u> </u>		

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON 670 - 0021

Sumner's Castle