

# ANNUAL SURVEYS.

42304

No. 918 Survey held at London Date, first Survey 14 Feb Last Survey 27 Feb 1883  
 No. in on the S Star of France Master H H Nelson  
 Reg. Book. 918 Tonnage { Net 1569 Built at Belfast When built 1877 Year. 11 Month. 11  
 Gross 1644 By whom built Harland & Wolff Owners J Barry & Co  
 Under Dk. 1475 Port belonging to Belfast Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Greens St & Vaseal (State Name of Dock.)

Last Survey, No. 41610 Port of Lon  
 Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "  
 Planksheers " Keelsons " Masts, Yards, &c. "  
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St  
 Topsides " Ceiling " Sails Good  
 Wales " Rudder " Anchors, No. of 3 Bcs. 22 & 24 lbs  
 Plank (Bottom) and Counter " Copper or Y.M. Cruited When put on new Cables Part on St Good  
 Engine Room Skylights " Caulking of " Hawsers and Warps "  
 Coal Bunkers, Openings, Lids, &c. " Bottom, Deck, & Waterways Good Standing and Running Rigging "  
 Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. She is now in an efficient state  
an eligible to remain as classed.  
The Society Freeboard now Painted on 8 March 83

Committee's Minute Friday, 9th March 18 83.  
 Character assigned SBH-100A  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) 5/- Paid 20-3-18 83

No.            Survey held at            Date, first Survey            Last Survey            18            
 No. in on the            Master             
 Reg. Book.            Year.            Month.             
 Tonnage { Net            Built at            When built             
 Gross            By whom built            Owners             
 Under Dk.            Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock            (State Name of Dock.)

Last Survey, No.            Port of            Classed             
 Present Condition of the  
 Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches            Windlass and Capstan             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings            Pumps             
 Lower Deck Beams & Fastenings            Ditto ditto at other places            Boats             
 Planksheers            Keelsons            Masts, Yards, &c.             
 Sheerstrakes            Clamps and Shelves            Condition, how ascertained             
 Topsides            Ceiling            Sails             
 Wales            Rudder            Anchors, No. of             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on            Cables             
 Engine Room Skylights            Caulking of            Hawsers and Warps             
 Coal Bunkers, Openings, Lids, &c.            Bottom, Deck, & Waterways            Standing and Running Rigging             
 Scuppers            Cargo and Main Hatchways            Hatches             
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
 Character assigned             
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid            18            
 LON 670-0024