

ANNUAL SURVEYS.

No. 108 on the Iron Screw "Fedele Primavese" Master A. P. Shilton
 Reg. Book. 108 Survey held at London Date, first Survey 6th March Last Survey 6th March 1883
 Tonnage Net 1067 Built at Newcastle When built 1881 Month 2nd
Gross 1638 By whom built Palmer's Co Owners J & R. Bovey
Under Dk. 1519 Port belonging to London Destined Voyage Shields, hence to Alexandria
 If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock
 (State Name of Dock.)

Last Survey, No. 41663 Port of Lon. Classed 100 A.1.
 Years assigned 8, 82 Character in Register Book.

Present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Rivets <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>D^o</u>	Breasthooks and Stemson <u>D^o</u>		Pumps <u>D^o</u>
Comings <u>D^o</u>	Transoms, Pointers, and Crutches <u>D^o</u>		Boats <u>D^o</u>
Upper Deck Beams & Fastenings <u>D^o</u>	Timbers of the Frame at the Openings <u>D^o</u>		Masts, Yards, &c. <u>D^o</u>
Lower Deck Beams & Fastenings <u>D^o</u>	Ditto ditto at other places <u>D^o</u>		Condition, how ascertained <u>from the deck</u>
Planksheers <u>D^o</u>	Keelsons <u>D^o</u>		Sails <u>good</u>
Sheerstrakes <u>D^o</u>	Clamps and Shells <u>D^o</u>		Anchors, No. of <u>3 B. 1 S. 2 K</u>
Topsides <u>D^o</u>	Ceiling <u>D^o</u>		Cables <u>good</u>
Wales <u>D^o</u>	Rudder <u>D^o</u>		Hawsers and Warps <u>D^o</u>
Plating <u>D^o</u>	Copper or Y.M. <u>When put on</u>		Standing and Running Rigging <u>D^o</u>
Plank (Bottom) and Counter <u>D^o</u>	Caulking of <u>good</u>		
	Bottom, Deck, & Waterways <u>good</u>		

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good.

General Observations, Opinion as to Class, &c.

The bottom has been examined and coated. Some rivets in the stem and in the rudder renewed. Two pintles of the rudder belished.
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Tuesday, 13th March. 1883.

Character assigned TRW 100 A.1

J. H. Truscott.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Master
 Reg. Book. (No. of Visits)
 Tonnage Net Built at When built Year Month
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Years assigned Character in Register Book.

Present Condition of the

Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shells <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u>When put on</u>	Standing and Running Rigging <u> </u>
	Caulking of <u> </u>	
	Bottom, Deck, & Waterways <u> </u>	

Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned



© 2021

Lloyd's Register

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(Insert Character precisely as in Register Book.)

Lon 670-0030