

ANNUAL SURVEYS.

Rec'd 29th March 1883
(Received at London Office,)
 42336

No. 565 on the Iron Ship Loch Kinnachar Master J. S. O'Hanne
 Reg. Book. 565 Net 1485 Built at Glasgow When built 1875 - 8
 Tonnage Gross 1554 Under Dk. 1362 By whom built J. G. Houston Owners Glasgow Shipping Company
 Port belonging to Glasgow Destined Voyage Poplar Dry Dock
 If Surveyed Afloat or in Dry Dock Poplar Dry Dock
(State Name of Dock.)

Last Survey, No. 41334 Port of London Classed 100 A 1
 Present Condition of the Decks good Treenails Rivets good S.S. Mel No. 1-80 3.82
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained by observation
 Topsides " Ceiling " Sails Sufficient
 Wales " Rudder pointed bushed Anchors, No. of 3 B, 1 S & 2 K
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1873 Cables part seen on deck good
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
This vessel has now been placed in dry dock the bottom examined and recoated with paint. She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Tuesday, 20th March, 1883.
 Character assigned JRM 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
27. 3. 83 Certificate (if required, to be sent as per margin) Paid 18

No. 155 on the Iron Ship Samuel Plimsoll Master Alexander Simpson
 Reg. Book. 155 Net 1444 Built at Aberdeen When built 1873 - 9
 Tonnage Gross 1510 Under Dk. 1343 By whom built W. Hood & Co Owners J. Thompson & Co
 Port belonging to Aberdeen Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Canal Dry Dock and Afloat
(State Name of Dock.)

Last Survey, No. 41320 Port of Lon Classed 100 A 1
 Present Condition of the Decks good Treenails Rivets good S.S. Lau No. 2-81 3.82
 Waterways " Breasthooks and Stemson " Windlass and Capstan good
 Comings " Transoms, Pointers, and Crutches " Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Masts, Yards, &c. "
 Planksheers " Keelsons " Condition, how ascertained by observation
 Sheerstrakes " Clamps and Shelves " Sails Sufficient
 Topsides " Ceiling " Anchors, No. of 3 B, 1 S & 2 K
 Wales " Rudder " Cables part seen on deck good
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1873 Hawsers and Warps Sufficient
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good

General Observations, Opinion as to Class, &c.
This vessel has now been placed in dry dock the bottom examined and recoated with paint. She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute Tuesday, 20th March, 1883.
 Character assigned JRM 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
27. 3. 83 Certificate (if required, to be sent as per margin) Paid 18

Form No. 100 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

