

# ANNUAL SURVEYS.

42346

No. 709 Survey held at London Date, first Survey 8 March Last Survey 8 March 1883  
(Received at London Office, 1/3/83)  
 No. in Reg. Book. on the SS Merkara Master Wood  
(No. of Visits)  
 Tonnage Net 1950 Gross 2971 Under Dk. 2919 Built at Dumbarton When built 1875 Year. 7 Month.  
 By whom built W. Bennett & Co Owners J. Macneil & P. Denny  
 Port belonging to Glasgow Destined Voyage Australia  
 If Surveyed Afloat or in Dry Dock Albert by SH  
(State Name of Dock.)

Last Survey, No. 41882 Port of London Classed 100A Years assigned. 10.82 Character in Register Book.  
SS Lon M. 75.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Character in Register Book.	<u>Good</u>
Waterways	"	Breasthooks and Stenson	"	Windlass and Capstan	<u>Good</u>
Comings	"	Transoms, Pointers, and Crutches	"	Pumps	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats	"
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c.	"
Planksheers	"	Keelsons	"	Condition, how ascertained	<u>From SH</u>
Sheerstrakes	"	Clamps and Shelves	"	Sails	<u>Good</u>
Topsides	"	Ceiling	"	Anchors, No. of <u>3 Bns 12 9 Kedges</u>	"
Wales	"	Rudder	"	Cables <u>Part on SH</u>	<u>Good</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Canted</u> When put on <u>run</u>	"	Hawsers and Warps	"
Engine Room Skylights <u>Good</u>	Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Scuppers <u>Good</u>	Standing and Running Rigging	"
General Observations, Opinion as to Class, &c.		Copper or Y.M. <u>Canted</u> When put on <u>run</u>		Cargo and Main Hatchways <u>Good</u>	Hatches <u>Good</u>

*Bottom to be coated  
 She is now in an efficient state  
 and eligible to remain as classed.*

Committee's Minute Thursday, 22nd March, 1883. Senhouse Martindale  
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
(No. of Visits)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
(No. of Visits)  
 Tonnage Net \_\_\_\_\_ Gross \_\_\_\_\_ Under Dk. \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
Year. Month.  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_ Years assigned. \_\_\_\_\_ Character in Register Book.

Present Condition of the Decks	Treenails	Character in Register Book.
Waterways	Breasthooks and Stenson	Windlass and Capstan
Comings	Transoms, Pointers, and Crutches	Pumps
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats
Lower Deck Beams & Fastenings	Ditto ditto at other places	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained
Sheerstrakes	Clamps and Shelves	Sails
Topsides	Ceiling	Anchors, No. of
Wales	Rudder	Cables
Plank (Bottom) and Counter	Copper or Y.M. _____ When put on _____	Hawsers and Warps
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____
General Observations, Opinion as to Class, &c.		Hatches _____

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18



The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

