

# ANNUAL SURVEYS.

42347

No.            Survey held at London Date, first Survey 7 March Last Survey 9 March 1883  
(Received at London Office, 13. 3. 83)  
 No. in Reg. Book. on the SS Glenartney Master J. Mattau  
(No. of Visits)  
 Tonnage { Net 400 Built at Glasgow When built 1873 Month. 9  
           { Gross 2143  
           { Under Dk. 2065 By whom built Sen & Glasco Owners W. Gregor & Co  
 Port belonging to Glasgow Destined Voyage China  
 If Surveyed Afloat or in Dry Dock Green Bay St  
(State Name of Dock.)

Last Survey, No. 41770 Port of London Classed 100 A. 9. 82  
Years assigned. Character in Register Book.  
 Present Condition of the  
 Decks Good Treenails Good Rivets Good  
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M. Coated When put on now  
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches             
 General Observations, Opinion as to Class, &c. Bottom & coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Thursday, 22nd March. 1883. Senhouse Martindale  
 Character assigned T.M.O.A. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid            18          

No.            Survey held at            Date, first Survey            Last Survey            18            
(No. of Visits)  
 No. in Reg. Book. on the            Master             
(No. of Visits)  
 Tonnage { Net            Built at            When built             
           { Gross             
           { Under Dk.            By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock             
(State Name of Dock.)

Last Survey, No.            Port of            Classed             
Years assigned. Character in Register Book.  
 Present Condition of the  
 Decks            Treenails             
 Waterways            Breasthooks and Stemson             
 Comings            Transoms, Pointers, and Crutches             
 Upper Deck Beams & Fastenings            Timbers of the Frame at the Openings             
 Lower Deck Beams & Fastenings            Ditto ditto at other places             
 Planksheers            Keelsons             
 Sheerstrakes            Clamps and Shelves             
 Topsides            Ceiling             
 Wales            Rudder             
 Plank (Bottom) and Counter            Copper or Y.M.            When put on             
 Caulking of Bottom, Deck, & Waterways             
 Engine Room Skylights            Coal Bunkers, Openings, Lids, &c.            Scuppers            Cargo and Main Hatchways            Hatches             
 General Observations, Opinion as to Class, &c.           

Committee's Minute            18            
 Character assigned            Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)            Paid            18          



ANNUAL SURVEYS

*Continued*

Class	Port of	Last Survey, No.	General Condition of the Vessel	Part belonging to the Government	Part belonging to the Merchant	Part belonging to the Charterer	Part belonging to the Crew	Part belonging to the Passengers	Part belonging to the Cargo	Part belonging to the Deck	Part belonging to the Mast	Part belonging to the Rig	Part belonging to the Sails	Part belonging to the Anchors	Part belonging to the Rigging	Part belonging to the Stores	Part belonging to the Tools	Part belonging to the Miscellaneous	
...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...

Class	Port of	Last Survey, No.	General Condition of the Vessel	Part belonging to the Government	Part belonging to the Merchant	Part belonging to the Charterer	Part belonging to the Crew	Part belonging to the Passengers	Part belonging to the Cargo	Part belonging to the Deck	Part belonging to the Mast	Part belonging to the Rig	Part belonging to the Sails	Part belonging to the Anchors	Part belonging to the Rigging	Part belonging to the Stores	Part belonging to the Tools	Part belonging to the Miscellaneous	
...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...	...

