

REPORT of SURVEY for REPAIRS, &c.

42362

(Received at London Office, 30. 3. 83)

No. in Survey held at London Date, first Survey March 20th Last Survey March 29th 1883
 g. Book. 501 on the Iron S.S. Soldindspektor Skie (formerly Duffess) Master O. Overaas
 TONNAGE under Tonnage Deck 313 Built at Whitby When built 1876
 Ditto of Spar Deck, or Avoning Deck
 Ditto of Poop
 Ditto of Raised Q. Dk.
 Ditto of Horses on Deck
 Ditto of Forecastle
 Gross Tonnage 417 Owners Mr Wolckmar Port belonging to Christiania
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 264 By whom built J. Turubull & Sons Destined Voyage
 If Surveyed Afloat ✓ in Dry Dock Canal Dock & West India Dock
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck 52 ft. Classed 90 A 1
S.S. Har No 2-82 9, 82
 Society's Load-Line (if assigned) as painted on Ship
 Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42349 Port London
 REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.

Change of Owners

| Present Condition of the | Particulars | Remarks |
|--|---------------------------------------|---------------------|
| Decks | Breasthooks and Stemson | } <u>Good</u> |
| Waterways | Transoms, Pointers, and Crutches | |
| Comings | Timbers of the Frame at the openings | |
| Upper Deck Beams & Fastenings | Ditto Ditto at other places | |
| Lower Deck Beams & Fastenings | Keelsons | |
| Planksheers | Clamps and Shelves | |
| Sheerstrakes | Ceiling | |
| Topsides | Rudder | |
| Wales | Copper (or Y.M.) When put on | |
| Plank (Bottom) and Counter | Cement (if Iron Ship) | |
| Engine Room Skylights | Caulking of Bottom, Deck, & Waterways | } <u>Good</u> |
| Coal Bunker, Openings, Lids, &c. | Scuppers | |
| General Observations, Opinion as to Class, &c. | Cargo and Main Hatchways | } <u>Good</u> |
| | Hatches | |
| | Windlass and Capstan | } <u>Good</u> |
| | Pumps | |
| | Boats | |
| | Masts, Yards, &c. | } <u>Good</u> |
| | Condition, how ascertained | |
| | Sails | } <u>Good</u> |
| | Anchors No. of | |
| | Cables | } <u>Sufficient</u> |
| | Hawsers and Warps | |
| | Standing & Running Rigging | } <u>Good</u> |
| | Hatches | |

This vessel recently taken over by Mr Robert Thompson from a Trust Company has again changed Owners as recorded above.

This fee has been paid for already upon No 42349

The Amount of Entry Fee ... £
 Special ... £
 Certificate (if required) to be sent as per margin... £

J. W. Miles
 Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £)
 Committee's Minute
 Character assigned

Tuesday, 3rd April, 1883.

JTW 90A



© 2021 Lloyd's Register Foundation