

ANNUAL SURVEYS.

42379

No. 107 Survey held at London Date, first Survey 16 March Last Survey 22 March 1883
 (Received at London Office, 24 83)
 No. in Reg. Book. on the SS Garth Castle Master _____ (No. of Visits _____)
 Net 2381 Built at Glasgow When built 1880 Year. 1880 Month. 12
 Tonnage Gross 3705 Under Dk. 3537 By whom built J Elder & Co Owners J Curme & Co
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock James I W & Co Afloat (State Name of Dock.)

Last Survey, No. 42119 Port of London Classed 100A1 1. 83
 Years assigned. Character in Register Book.

Present Condition of the	Treenails	Character in Register Book.
Decks <u>good</u>	<u>Rivets</u>	<u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Windlass and Capstan <u>good</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Pumps <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Boats <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Masts, Yards, &c. <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Condition, how ascertained <u>From Str</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Sails <u>good</u>
Wales <u>"</u>	Rudder <u>"</u>	Anchors, No. of <u>4 Bns. 12 & Kedgs</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Copper</u> When put on <u>run</u>	Cables <u>Castor Str</u>
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Hawsers and Warps <u>"</u>
Coal Bunkers, Openings, Lids, &c. <u>"</u>	Scuppers <u>good</u>	Standing and Running Rigging <u>"</u>
General Observations, Opinion as to Class, &c. <u>Bottom to be coated.</u>		Cargo and Main Hatchways <u>good</u> Hatches <u>"</u>

She is now in an efficient state and eligible to remain as classed. Chain cables ranged for the Government Surveys & examined by me 300 fathoms good

Committee's Minute Tuesday, 10th April 1883.
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Mastindale
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 (No. of Visits _____)
 No. in Reg. Book. on the _____ Master _____
 Year. _____ Month. _____
 Tonnage Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Years assigned. Character in Register Book.

Present Condition of the	Treenails	Character in Register Book.
Decks _____	<u>Treenails</u>	
Waterways _____	Breasthooks and Stemson _____	Windlass and Capstan _____
Comings _____	Transoms, Pointers, and Crutches _____	Pumps _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Boats _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Masts, Yards, &c. _____
Planksheers _____	Keelsons _____	Condition, how ascertained _____
Sheerstrakes _____	Clamps and Shelves _____	Sails _____
Topsides _____	Ceiling _____	Anchors, No. of _____
Wales _____	Rudder _____	Cables _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Hawsers and Warps _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Standing and Running Rigging _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Cargo and Main Hatchways _____ Hatches _____
General Observations, Opinion as to Class, &c. _____		

Committee's Minute _____ 18
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) Paid 18



Committee's Minute

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

