

ANNUAL SURVEYS.

42397

No. Survey held at London Date, first Survey 19th March Last Survey 12 April 1883
(Received at London Office, 12 - 4 - 83)

No. in on the BK Costa Rica Packet Master J Hemsworth
Reg. Book. 1247 (No. of Visits)

Tonnage Net 531 Built at Guernsey When built 1861 Year. 7 Month.
Gross 531 Under Dk. 503 By whom built Owners G Hemsworth

Port belonging to London Destined Voyage Rockhampton
 If Surveyed Afloat or in Dry Dock East India Dock
(State Name of Dock.)

Last Survey, No. 41266 Port of Lon Years assigned. 17 A. 3. 82. Character in Register Book.
Cont Lon June 79 - 11 yrs

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Windlass and Capstan <u>Good</u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Pumps <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Boats <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Masts, Yards, &c. <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Condition, how ascertained <u>From SA</u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Sails <u>Good</u>
Topsides <u> </u>	Ceiling <u> </u>	Anchors, No. of <u>3 Ans. 12 & 12 lbs</u>
Wales <u> </u>	Rudder <u> </u>	Cables <u>Part on SA</u> <u>Good</u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u>Y Metal</u> When put on <u>1882</u>	Hawsers and Warps <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u> </u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, 13th April, 1883. Senhouse Martindale
 Character assigned J M Cooper 11A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)

No. in on the Master
Reg. Book. (No. of Visits)

Tonnage Net Built at When built Year. Month.
Gross Under Dk. By whom built Owners


Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Years assigned. Character in Register Book.

Present Condition of the Decks <u> </u>	Treenails <u> </u>	
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Windlass and Capstan <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Pumps <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Boats <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Masts, Yards, &c. <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Condition, how ascertained <u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Sails <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Anchors, No. of <u> </u>
Wales <u> </u>	Rudder <u> </u>	Cables <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Hawsers and Warps <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	Standing and Running Rigging <u> </u>
Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>	Cargo and Main Hatchways <u> </u>
Hatches <u> </u>		

General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Lon 670-0131