

ANNUAL SURVEYS.

No. 207 Survey held at London Date, first Survey 28th Feb Last Survey 28th March 1883
(Received at London Office, 18th April 83)
No. in on the Barque "Fitzroy" Master G. Bush
Reg. Book. 207 (No. of Visits 1)
Tonnage { Net 573 Built at Sunderland When built 1863 Month. 9th
Gross 573
Under Dk. 511 By whom built G. Peverall Owners L. Wilson
Port belonging to London Destined Voyage Liver River
If Surveyed Afloat or in Dry Dock In the Upper Globe Dry Dock
(State Name of Dock)

Last Survey, No. 41195 Port of Lon
Present Condition of the
Decks good Treenails good
Waterways de Breasthooks and Stemson de
Comings de Transoms, Pointers, and Crutches de
Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
Lower Deck Beams & Fastenings de Ditto ditto at other places de
Planksheers de Keelsons de
Sheerstrakes de Clamps and Shelves de
Topsides de Ceiling de
Wales de Rudder de
Plank (Bottom) and Counter de Copper or Y.M. good When put on 282
Engine Room Skylights de Caulking of good
Coal Bunkers, Openings, Lids, &c. good Bottom, Deck, & Waterways good
Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. The bottom has been sighted & the yellow metal sheathing painted. Two davits renewed fore taken out, straightened & replaced. An anchor now supplied in place of the larger kedge which was missing - marks on anchor are 4-2-20 & 9120 but the certificate of test has not been produced - it is stated to have been left on board the vessel, which has gone to sea. This vessel appears to be in good & efficient condition & eligible to remain as classed but it is submitted that the certificate of test for the kedge anchor in question be produced on the return from the voyage.
Committee's Minute Friday, 20th April 1883. J. H. Truscott.
Character assigned note book Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 207 Survey held at London Date, first Survey 28th Feb Last Survey 28th March 1883
(Received at London Office, 18th April 83)
No. in on the Barque "Fitzroy" Master G. Bush
Reg. Book. 207 (No. of Visits 1)
Tonnage { Net 573 Built at Sunderland When built 1863 Month. 9th
Gross 573
Under Dk. 511 By whom built G. Peverall Owners L. Wilson
Port belonging to London Destined Voyage Liver River
If Surveyed Afloat or in Dry Dock In the Upper Globe Dry Dock
(State Name of Dock)
Last Survey, No. 41195 Port of Lon
Present Condition of the
Decks good Treenails good
Waterways de Breasthooks and Stemson de
Comings de Transoms, Pointers, and Crutches de
Upper Deck Beams & Fastenings de Timbers of the Frame at the Openings de
Lower Deck Beams & Fastenings de Ditto ditto at other places de
Planksheers de Keelsons de
Sheerstrakes de Clamps and Shelves de
Topsides de Ceiling de
Wales de Rudder de
Plank (Bottom) and Counter de Copper or Y.M. good When put on 282
Engine Room Skylights de Caulking of good
Coal Bunkers, Openings, Lids, &c. good Bottom, Deck, & Waterways good
Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. The bottom has been sighted & the yellow metal sheathing painted. Two davits renewed fore taken out, straightened & replaced. An anchor now supplied in place of the larger kedge which was missing - marks on anchor are 4-2-20 & 9120 but the certificate of test has not been produced - it is stated to have been left on board the vessel, which has gone to sea. This vessel appears to be in good & efficient condition & eligible to remain as classed but it is submitted that the certificate of test for the kedge anchor in question be produced on the return from the voyage.
Committee's Minute Friday, 20th April 1883. J. H. Truscott.
Character assigned note book Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18