

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, Tuesday, 17th April 1883)

Survey held at London Date, first Survey 5th April Last Survey 14th April 1883
 on the Iron S.S. "Ashburne" (No. of Visits)
 Master J. Lambert
 Tonnage Deck 2010 YEAR. MONTH.
 Spar Deck, or Awning Deck Built at Sunderland When built 1879 3
 Poop Owners J. O. Barwick & Co Port belonging to Sunderland
 Raised Qr. Dk. Residence
 Houses on Deck By whom built Short Bros Destined Voyage East London via Newcastle
 Forecastle Tonnage 2489 If Surveyed Afloat or in Dry Dock Commercial dry dock
 Tonnage, as per Rule (State Name of Dock)
 Tonnage, cut on Beam Room
 as at Mer, cut on Bm. 1613
 of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Classified 100 A 1

Survey, No 27686 Port Liv.

REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.

Through damage
the part of them straightened. 2 plates of head on Starboard side
and on Port side. one new and one straightened. one plate
below sheer stake Starboard bow new. new Bowsprit and
new head. new Cat davit & stuffing box to same.
Poop stanchions repaired and one new piece of Poop rail
new other minor damages made good.
Bottom painted and Rudder plating repaired

new steel 2" Hawser. a 6" hemp & Manila Hawser and 15 fms
able to be supplied on her arrival at Newcastle. whether she
proceeds from this Port

Condition of the

Condition of the	Good	Repaired	Good	Good
Transoms	—	—	—	—
Breasthooks and Stems	—	—	—	—
Transoms, Pointers, and Crutches	—	—	—	—
Timbers of the Frame at the openings	—	—	—	—
Ditto Ditto at other places	—	—	—	—
Keelsons	—	—	—	—
Clamps and Shells	—	—	—	—
Ceiling	—	—	—	—
Rudder	—	—	—	—
Copper (or Y.M.) When put on (State if on Felt.)	—	—	—	—
Cement (if Iron Ship)	—	—	—	—
Caulking of Bottom, Deck, & Waterways	—	—	—	—
Windlass and Capstan	—	—	—	—
Pumps	—	—	—	—
Boats	—	—	—	—
Masts, Yards, &c.	—	—	—	—
Condition, how ascertained	—	—	—	—
Sails	—	—	—	—
Anchors	—	—	—	—
Cables	—	—	—	—
Hawsers and Warps	—	—	—	—
Standing & Running Rigging	—	—	—	—
Cargo and Main Hatchways	—	—	—	—
Hatches	—	—	—	—
Bottom and Counter	—	—	—	—
Room Skylights	—	—	—	—
Coal Bunker, Openings, Lids, &c.	—	—	—	—
Scuppers	—	—	—	—

Observations, Opinion as to Class, &c.

She is now in good condition and eligible to
again as classed when the above named stores are supplied
Newcastle

Wm. L. Davey
John H. Heck.

Amount of Entry Fee ... £ : : : received by me, }
14/4/83 Special ... £ / : / : - 188

Certificate (if required) } £ : :
 to be sent as per margin...

Expenses, if any, £

Committee's Minute

Character assigned

Sp Damage 43. 31-

Tuesday, 24th April 1883.

100 A 1

J. H. Heck

ROBT. EDM. TAYLOR & SON, Commercial Steam Printers, 19, Old Street, Goswell Road, London.



© 2021

Lloyd's Register

Foundation

CON 670-0163

(Insert Character precisely as in Register Book.)