

# ANNUAL SURVEYS.

42430

No. \_\_\_\_\_ Survey held at London Date, first Survey 13 March Last Survey 16 April 1883  
(Received at London Office, Tuesday, 17th April, 1883.)  
 No. in Reg. Book. on the SS Scotland Master Sackhurst  
(No. of Visits)  
345 Net 1684 Built at Kinghorn When built 1869 9  
Year. Month.  
 Tonnage Gross 2645 By whom built J Key Owners Jemperley Carter & Carter  
Under Dk. 1705  
 Port belonging to London Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock Afloat by Mr Vassant  
(State Name of Dock.)

Last Survey, No. 41634 Port of London Classed 100 A 1 882  
Years assigned. Character in Register Book.  
SS Lon M.S. 882

Present Condition of the Decks sd Treennails sd  
 Waterways sd Breasthooks and Stemson sd  
 Comings sd Transoms, Pointers, and Crutches sd  
 Upper Deck Beams & Fastenings sd Timbers of the Frame at the Openings sd  
 Lower Deck Beams & Fastenings sd Ditto ditto at other places sd  
 Planksheers sd Keelsons sd  
 Sheerstrakes sd Clamps and Shelves sd  
 Topsides sd Ceiling sd  
 Wales sd Rudder sd  
 Plank (Bottom) and Counter sd Copper or Y.M. Coated When put on sd  
 Caulking of Bottom, Deck, & Waterways sd  
 Engine Room Skylights sd Coal Bunkers, Openings, Lids, &c. sd Scuppers sd Cargo and Main Hatchways sd Hatches sd  
 General Observations, Opinion as to Class, &c. Bottom to coated, she is now in an efficient state and likely to remain as classed.

Committee's Minute Tuesday, 24th April 1883. Senhouse Mastheadale  
 Character assigned 100 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
(No. of Visits)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
Year. Month.  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. Character in Register Book.

Present Condition of the Decks \_\_\_\_\_ Treennails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid \_\_\_\_\_ 18 \_\_\_\_\_



Form No. 3 for Annual Survey. (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.