

# ANNUAL SURVEYS.

42432

No. 13 Survey held at London Date, first Survey 10 April Last Survey 10 April 1883  
 (Received at London Office, 14/4/83)  
 No. in Reg. Book. on the SS El Dorado Master Bonifacio  
 (No. of Visits 7)  
 Tonnage { Net 864 Built at N Shields When built 1882  
 Gross 1343 By whom built N Smith Owners Scrutton & Sons & Co.  
 Under Dk. 1111 Port belonging to London Destined Voyage Samarara  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock (State Name of Dock.)

Last Survey, No. 16194 Port of Rio de Janeiro Classed 100 A 1 3, 82  
 Years assigned. Character in Register Book.

Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom in contact  
She is now in an efficient state  
and eligible to remain as classed.

Committee's Minute Tuesday, 24th April 1883.  
 Character assigned 100 A 1  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Certificate (if required, to be sent as per margin) Paid 18

No. 13 Survey held at London Date, first Survey 10 April Last Survey 10 April 1883  
 (No. of Visits 7)  
 No. in Reg. Book. on the SS El Dorado Master Bonifacio  
 (No. of Visits 7)  
 Tonnage { Net 864 Built at N Shields When built 1882  
 Gross 1343 By whom built N Smith Owners Scrutton & Sons & Co.  
 Under Dk. 1111 Port belonging to London Destined Voyage Samarara  
 If Surveyed Afloat or in Dry Dock Greens Dry Dock (State Name of Dock.)

Last Survey, No. 16194 Port of Rio de Janeiro Classed 100 A 1 3, 82  
 Years assigned. Character in Register Book.

Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways Good Breasthooks and Stemson Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shelves Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or Y.M. Copper When put on new  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c. Bottom in contact  
She is now in an efficient state  
and eligible to remain as classed.

Committee's Minute 18  
 Character assigned 100 A 1  
 Surveyor to Lloyd's Register of British and Foreign Shipping. Senhouse Martindale  
 Certificate (if required, to be sent as per margin) Paid 18



(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

(Form No. 3 for Annual Survey, when there are no repairs. 4000—25/4/82.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)



Survey held at

Date, first Survey

Class

By whom held

When held

Owners

Part of

Part belonging to

Part of

Part of

Class

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of

Part of