

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey 10th April Last Survey 20th April 1883
 (Received at London Office, 21. 4. 83)
 No. in on the SS Hawthorns Master Scott
 Reg. Book. 166 (No. of Visits)
 Net 473 Built at Newcastle When built 1861 Month. 8
 Tonnage 752 By whom built Palmer & Co Owners J. Fenwick & Son
 Under Dk. 639 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Pontoon Victoria
 (State Name of Dock.)

Last Survey, No. 41437 Port of London
 Present Condition of the
 Decks Good Treenails Pine Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Copper When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 General Observations, Opinion as to Class, &c. Rubber Bushes & Brass re-rivets. Bottoms under
She is now in an efficient state
and eligible to remain as classed,
She has 4 Bower anchors

Committee's Minute Friday, 27th April, 1883. Senhouse Martin Dale
 Character assigned B.S. 4, 83 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 (No. of Visits)
 No. in on the Master
 Reg. Book. (No. of Visits)
 Net Built at When built Year. Month.
 Tonnage By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

ANNUAL SURVEYS

Handwritten: 1871

No.	Survey held at	Date, first survey	Master	When built	Owner	Part of	Class
1							
2							
3							
4							
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							
29							
30							
31							
32							
33							
34							
35							
36							
37							
38							
39							
40							
41							
42							
43							
44							
45							
46							
47							
48							
49							
50							
51							
52							
53							
54							
55							
56							
57							
58							
59							
60							
61							
62							
63							
64							
65							
66							
67							
68							
69							
70							
71							
72							
73							
74							
75							
76							
77							
78							
79							
80							
81							
82							
83							
84							
85							
86							
87							
88							
89							
90							
91							
92							
93							
94							
95							
96							
97							
98							
99							
100							



© 2021

Lloyd's Register
Foundation