

# ANNUAL SURVEYS.

No. 965 Survey held at London Date, first Survey and Last Survey 20 April 1883  
 No. in on the Iron S. "Collingwood" Master Forbes  
 Reg. Book. 965 Tonnage 1011 Built at Aberdeen When built 1872 - 6m  
 By whom built W Hood & Co Owners Devitt & Moore  
 Port belonging to London Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock Union Dry Dk

Last Survey, No. 41499 Port of Lon Classed S. S. - Lon. No. 2. 80  
 Years assigned. 100 A. 1  
 Character in Register Book. 5-82-

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	<u>S. S. - Lon. No. 2. 80</u>
Waterways	<u>Do</u>	Breasthooks and Stemson		<u>Do</u>	
Comings	<u>Do</u>	Transoms, Pointers, and Crutches		<u>Do</u>	Windlass and Capstan
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the Openings		<u>Do</u>	Pumps
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto ditto at other places		<u>Do</u>	Boats <u>4 No</u>
Planksheers		Keelsons		<u>Do</u>	Masts, Yards, &c.
Sheerstrakes	<u>Do</u>	Clamps and Shelves		<u>Do</u>	Condition, how ascertained <u>from deck</u>
Topsides	<u>Do</u>	Ceiling		<u>Do</u>	Sails
Wales	<u>Do</u>	Rudder		<u>Do</u>	Anchors, No. of <u>3 B. 15. 2K</u>
Plank (Bottom) and Counter	<u>Do</u>	Copper or Y.M. Cement When put on <u>72</u>			Cables <u>when seen</u>
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		<u>Good</u>	Hawsers and Warps <u>4 No</u>
Coal Bunker, Openings, Lids, &c.		Scuppers		<u>Good</u>	Standing and Running Rigging
General Observations, Opinion as to Class, &c.		Cargo and Main Hatchways		<u>Good</u>	Hatches

The bottom sighted and recoated.  
Ballast in main hold  
She is now in good condition and eligible in our opinion to remain as classed

Committee's Minute Friday, 27th April, 1883.

Character assigned TRW 100A 1

John H Heck.  
Will B. Davey  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18

No.            Survey held at            Date, first Survey            Last Survey 18

No. in on the            Master             
 Reg. Book.            Tonnage            Built at            When built             
 By whom built            Owners             
 Port belonging to            Destined Voyage             
 If Surveyed Afloat or in Dry Dock           

Last Survey, No.            Port of            Classed             
 Years assigned.            Character in Register Book.           

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors, No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper or Y.M. When put on	Standing and Running Rigging
Engine Room Skylights	Caulking of Bottom, Deck, & Waterways	Hatches
Coal Bunkers, Openings, Lids, &c.	Scuppers	
General Observations, Opinion as to Class, &c.		

Committee's Minute 18

Character assigned           

Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required) 18