

ANNUAL SURVEYS.

42454

No. Survey held at London Date, first Survey and Last Survey 19 April 1883
(Received at London Office Rec'd 22/4/1883)
 No. in Reg. Book. 406 on the Iron S.S. Wolviston Master J Cooper
(No. of Visits)
 Tonnage 1136 Net Built at W. Hartlepool When built 1879 - 10 Month.
Gross 1758 Under Dk. 1387 By whom built W Gray & Co Owners W. Hartlepool S. N. Co
 Port belonging to W. Hartlepool Destined Voyage Adeu via Cardiff
 If Surveyed Afloat or in Dry Dock Commercial Dry Dk
(State Name of Dock.)

Last Survey, No. 4989 Port of Ldk Classed Years assigned. 100 A1 Character in Register Book. 9-82

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	
Waterways	<u>Do</u>	Breasthooks and Stemson	<u>Do</u>	Windlass and Capstan
Comings	<u>Do</u>	Transoms, Pointers, and Crutches	<u>Do</u>	Pumps
Upper Deck Beams & Fastenings	<u>Do</u>	Timbers of the Frame at the Openings	<u>Do</u>	Boats <u>4 No</u>
Lower Deck Beams & Fastenings	<u>Do</u>	Ditto ditto at other places	<u>Do</u>	Masts, Yards, &c.
Planksheers	<u>Do</u>	Keelsons	<u>Do</u>	Condition, how ascertained <u>from deck</u>
Sheerstrakes	<u>Do</u>	Clamps and Shelves	<u>Do</u>	Sails
Topsides	<u>Do</u>	Ceiling	<u>Do</u>	Anchors, No. of <u>3 B. 1 S. 2 R.</u>
Wales	<u>Do</u>	Rudder	<u>Do</u>	Cables <u>when seen</u> <u>Good</u>
Plank (Bottom) and Counter	<u>Do</u>	Copper or Y.M. Cement When put on <u>79</u>		Hawsers and Warps <u>6 No</u> <u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging <u>Do</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Scuppers	<u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Hatches	<u>Good</u>			

General Observations, Opinion as to Class, &c.
The rudder pintles rebushed and the bottom sighted and repainted.
She is now in good condition and eligible in my opinion to remain as classed.

Committee's Minute Tuesday, 1st May, 1883. John H Heck
 Character assigned JH 100 A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
 No. in Reg. Book. on the Master
Year. Month.
 Tonnage Net Built at When built
Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the Decks		Treenails		
Waterways		Breasthooks and Stemson		Windlass and Capstan
Comings		Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places		Masts, Yards, &c.
Planksheers		Keelsons		Condition, how ascertained
Sheerstrakes		Clamps and Shelves		Sails
Topsides		Ceiling		Anchors, No. of
Wales		Rudder		Cables
Plank (Bottom) and Counter		Copper or Y.M. When put on		Hawsers and Warps
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c.		Scuppers		Cargo and Main Hatchways
Hatches				

General Observations, Opinion as to Class, &c.
 Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



L00670-0197