

# ANNUAL SURVEYS.

No. 14 Survey held at London Date, first Survey 25<sup>th</sup> Apr Last Survey 27<sup>th</sup> Apr 1883  
 No. in Reg. Book. 14 on the Sen S. "Hood Beaband" Master H. R. Page  
 Tonnage { Net 1624 Built at Middlebros When built 1882 Month 8  
 Gross 2403 Under Dk. 2257 By whom built R Dixon Owners Stoomvaart Maatschappij  
 Port belonging to Rotterdam Destined Voyage Rotterdam  
 If Surveyed Afloat or in Dry Dock Leimekiln dry Dock  
 (State Name of Dock.)

Last Survey, No. 5004 Port of Stk Classed 100A1  
 Present Condition of the Decks Good Reasonable Good  
 Waterways Good Breasthooks Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shells Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or F.M. Cement When put on 1882  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

Bottom recoated. Deck recaulked and inside of plating cleaned and oiled. She is now in good condition and eligible in my opinion to continue as Classed

Committee's Minute FRIDAY 11 MAY 1883 18  
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. 182 Survey held at London Date, first Survey and Last Survey 1<sup>st</sup> May 1883  
 No. in Reg. Book. 182 on the Sen S. "Bedale" Master J W Hick  
 Tonnage { Net 818 Built at S Shields When built 1879 Month 7  
 Gross 1267 Under Dk. 1029 By whom built I Beadhead Owners P. Hick & Co  
 Port belonging to Scarboro Destined Voyage Tajawoy via Cardiff  
 If Surveyed Afloat or in Dry Dock Afloat Commercial Dock  
 (State Name of Dock.)

Last Survey, No. 5537 Port of Rph Classed 100A1  
 Present Condition of the Decks Good Reasonable Good  
 Waterways Good Breasthooks Good  
 Comings Good Transoms, Pointers, and Crutches Good  
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good  
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good  
 Planksheers Good Keelsons Good  
 Sheerstrakes Good Clamps and Shells Good  
 Topsides Good Ceiling Good  
 Wales Good Rudder Good  
 Plank (Bottom) and Counter Good Copper or V.M. Cement When put on 1879  
 Caulking of Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good  
 General Observations, Opinion as to Class, &c.

She appears where seen in good condition and in my opinion eligible to continue as Classed

Committee's Minute FRIDAY 11 MAY 1883 18  
 Character assigned 100A1 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Wille & L. Davey  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18  
 LONB70-0223