

ANNUAL SURVEYS.

TUESDAY 15 MAY 1883

No. 42499 Survey held at London Date, first Survey — Last Survey 4th May 1883
(Received at London Office, —)
No. in on the Iron S.S. "Chamois" Master J. Hodgson
Reg. Book. 500 No. of Visits —
Tonnage Net 884 Built at Hartlepool When built 1878 9
Gross 1382 Under Dk. 1099 By whom built — Owners Jackson Bros & Co
Port belonging to Hartlepool Destined Voyage Meditⁿ via Cardiff
If Surveyed Afloat or in Dry Dock Commercial dry Dk
(State Name of Dock.)

Last Survey, No. 41631a Port of Lon
Present Condition of the
Decks Good Tracails Ruek Good
Waterways — Breasthooks and Stems —
Comings — Transoms, Pointers, and Crutches —
Upper Deck Beams & Fastenings — ~~Timbers~~ of the Frame at the Openings —
Lower Deck Beams & Fastenings — ~~Bits~~ ditto at other places —
Planksheers — Keelsons —
Sheerstrakes — Clamps and Shells —
Topsides — Ceiling —
Wales — Rudder —
Plank (Bottom) and Counter — Copper or Y.M. Cement When put on 1878
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Bottom coated with Black Varnish. She appears in good condition and eligible in my opinion to continue as classed

Committee's Minute

FRIDAY 25 MAY 1883

18

Character assigned

100A

Certificate (if required, to be sent as per margin) Paid 18

W. B. Davy
Surveyor to Lloyd's Register of British and Foreign Shipping.

No. — Survey held at London Date, first Survey 11th Apr Last Survey 13th Apr 1883
(No. of Visits —)
No. in on the Iron S.S. "Dickwick" Master J. Rhoades
Reg. Book. 367 No. of Visits —
Tonnage Net 731 Built at Sunderland When built 1871 8
Gross 1141 Under Dk. 899 By whom built W. Pile & Co Owners G. Bell & Co
Port belonging to H. Shields Destined Voyage Jamaica
If Surveyed Afloat or in Dry Dock Union dry Dk
(State Name of Dock.)

Last Survey, No. 16428 Port of Ruek
Present Condition of the
Decks Good Tracails Ruek Good
Waterways — Breasthooks and Stems —
Comings — Transoms, Pointers, and Crutches —
Upper Deck Beams & Fastenings — ~~Timbers~~ of the Frame at the Openings —
Lower Deck Beams & Fastenings — ~~Bits~~ ditto at other places —
Planksheers — Keelsons —
Sheerstrakes — Clamps and Shells —
Topsides — Ceiling —
Wales — Rudder replaced
Plank (Bottom) and Counter — Copper or Y.M. Cem When put on 1871
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
General Observations, Opinion as to Class, &c. Rudder replaced and bottom recoated. She is now in good condition and in my opinion eligible to continue as classed

Committee's Minute

FRIDAY 25 MAY 1883

18

Character assigned

90A

Certificate (if required, to be sent as per margin) Paid 18

W. B. Davy
Surveyor to Lloyd's Register of British and Foreign Shipping.Lloyd's Register
Foundations
20670-0258