

ANNUAL SURVEYS.

42501
FRIDAY 11 MAY 1883

No. 1067 Survey held at London Date, first Survey 1st May Last Survey 1st May 1883
(Received at London Office, FRIDAY 11 MAY 1883)
No. in on the Iron Scw. "Congella". Master R. Elwood.
Reg. Book. 1067 Net 1041 Built at Sunderland When built 1881 Year. 12 Month. 12
Tonnage Gross 1597 By whom built W. Doreford & L. Owners Bullard, King & Co
Under Dk. 1569 Port belonging to London. Destined Voyage Natal.
If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock.
(State Name of Dock.)

Last Survey, No. 42186 Port of Lon Classed 100 A.1
Years assigned. 1, 83.
Character in Register Book.
Present Condition of the
Decks good Treennails Rivets - good
Waterways D- Breasthooks and Stemson D-
Comings D- Transoms, Pointers, and Crutches D-
Upper Deck Beams & Fastenings D- Timbers of the Frame at the Openings D-
Lower Deck Beams & Fastenings D- Ditto ditto at other places D-
Planksheers D- Keelsons D-
Sheerstrakes D- Clamps and Shelves D-
Topsides D- Ceiling D-
Wales D- Rudder D-
Plank (Bottom) and Counter D- Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways good
Windlass and Capstan good
Pumps D-
Boats D-
Masts, Yards, &c. D-
Condition, how ascertained from the deck
Sails good
Anchors, No. of 3 B. 1 P. 2 K
Cables good
Hawsers and Warps D-
Standing and Running Rigging D-
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. The bottom has been examined and coated.
This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 25 MAY 1883 18
Character assigned 100 A.1 J. H. Truscott
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
No. in on the Master
Reg. Book. Year. Month.
Tonnage { Net Built at When built
 { Gross By whom built Owners
 { Under Dk.
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)
Last Survey, No. Port of Classed
Years assigned. Character in Register Book.
Present Condition of the
Decks Treennails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Caulking of Bottom, Deck, & Waterways
Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18