

ANNUAL SURVEYS.

42503

No. Survey held at London Date, first Survey 17 April Last Survey 8 May 1883
(Received at London on)
 No. in Reg. Book. 86 on the SS Warwick Castle Master Robinson
(No. of Visits)
 Tonnage Net 1852 Built at Glasgow When built 1877 Year. Month. 8
 Gross 2957 By whom built R Napier & Co Owners J Currie
 Under Dk. 2869
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock James J W & Co afloat.
(State Name of Dock.)

Last Survey, No. 42226 Port of Low
 Present Condition of the
 Decks Good Treenails Good Rivets Good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on
 Caulking of
 Bottom, Deck, & Waterways
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches
 General Observations, Opinion as to Class, &c. Bottom &c coated.
She is now in an efficient state
and eligible to remain as closed.
The Chain Cables have been ranged for the Government
surveyors & have been examined by one, 300 fathom in all.

Classed 100A Years assigned. 1883 Character in Register Book. SS Low M/82.

Committee's Minute FRIDAY 18 MAY 1883 18 Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
 No. in Reg. Book. on the Master
(No. of Visits)
 Tonnage Net Built at When built Year. Month.
 Gross By whom built Owners
 Under Dk.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. Coated When put on
 Caulking of
 Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery...
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (If a Steam Ship, when there are no repairs. 4000-20/3/82.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)



LON 670-0272

