

ANNUAL SURVEYS.

* 42507

No. Survey held at London Date, first Survey 12 March Last Survey 23 April 1883
(Received at London Office WEDNESDAY 13 MAY 1883)
 No. in Reg. Book. on the Bk "Bureau" Master J. Wyrell
(No. of Visits)
334 Tonnage Net 526 Built at Sunderland When built 1869 - 8
Gross 542 Under Dk. 506 By whom built W Pile & Co Owners J. B. Walker
 Port belonging to London Destined Voyage Launceston
 If Surveyed Afloat or in Dry Dock Linckhila Dry Dock & afloat.
(State Name of Dock.)

Last Survey, No. 42492 Port of Lon Classed 19 Years assigned. 5-82 Character in Register Book. A1

Present Condition of the			
Decks	<u>Good</u>	Treenails <u>Boths when run</u>	<u>Good</u>
Waterways	<u>5</u>	Breasthooks and Stenson	<u>5</u>
Comings	<u>5</u>	Transoms, Pointers, and Crutches	<u>5</u>
Upper Deck Beams & Fastenings	<u>5</u>	Timbers of the Frame at the Openings	<u>5</u>
Lower Deck Beams & Fastenings	<u>5</u>	Ditto ditto at other places	<u>5</u>
Planksheers	<u>5</u>	Keelsons	<u>5</u>
Sheerstrakes	<u>5</u>	Clamps and Shelves	<u>5</u>
Topsides	<u>5</u>	Ceiling	<u>5</u>
Wales	<u>5</u>	Rudder	<u>5</u>
Plank (Bottom) and Counter <u>(part run)</u>	<u>5</u>	Copper or Y.M. <u>on fut</u> When put on <u>81</u>	
Engine Room Skylights	<input checked="" type="checkbox"/>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<input checked="" type="checkbox"/>	Scuppers	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>The bottom sighted & the yellow metal repaired at a few places. Ballast in holds under main hatchway.</u>		

She is as far as could be seen in good condition & eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 18 MAY 1883 18 John H Heck.
 Character assigned DRM 19 A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
 No. in Reg. Book. on the Master
(No. of Visits)
 Tonnage Net Built at When built
Gross Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed Years assigned. Character in Register Book.

Present Condition of the			
Decks		Treenails	
Waterways		Breasthooks and Stenson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings		Ditto ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper or Y.M. <u> </u> When put on <u> </u>	
Engine Room Skylights	<input type="checkbox"/>	Caulking of Bottom, Deck, & Waterways	
Coal Bunkers, Openings, Lids, &c.	<input type="checkbox"/>	Scuppers	
General Observations, Opinion as to Class, &c.	<u> </u>		

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid

(If a Steam Ship, state if a Report is also sent on the Machinery) (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 400-56/4/82.) (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.) (Insert Character precisely as in Register Book.)

