

# ANNUAL SURVEYS.

No. 718 Survey held at London Date, first Survey 10<sup>th</sup> May Last Survey 10<sup>th</sup> May 1883  
(Received at London Office, TUESDAY 15 MAY 1883)  
No. in Reg. Book. on the Iron Barque Anglo Norman Master A. Davidson  
Tonnage { Net 822 Built at Port Glasgow When built 1876 Year. 1<sup>st</sup>  
Gross 864 By whom built Russell & Co Owners Frost & Co  
Under Dk. 755 Port belonging to London Destined Voyage Sydney  
If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock  
(State Name of Dock.)

Last Survey, No. 26180 Port of London Classed 100 A.1.  
Years assigned. 3, 80 Character in Register Book.

Present Condition of the			
Decks	<u>good</u>	<u>Treenails</u>	<u>good</u>
Waterways	<u>Do</u>	<u>Breasthooks and Stemson</u>	<u>Do</u>
Comings	<u>Do</u>	<u>Transoms, Pointers, and Crutches</u>	<u>Do</u>
Upper Deck Beams & Fastenings	<u>Do</u>	<u>Timbers of the Frame at the Openings</u>	<u>Do</u>
Lower Deck Beams & Fastenings	<u>Do</u>	<u>Ditto ditto at other places</u>	<u>Do</u>
Planksheers	<u>Do</u>	<u>Keelsons</u>	<u>Do</u>
Sheerstrakes	<u>Do</u>	<u>Clamps and Shelves</u>	
Topsides	<u>Do</u>	<u>Ceiling</u>	<u>Do</u>
Wales	<u>Do</u>	<u>Rudder</u>	<u>Do</u>
Plank (Bottom) and Counter	<u>Do</u>	<u>Copper or Y.M.</u>	<u>When put on</u>
Engine Room Skylights		<u>Caulking of</u>	
		<u>Bottom, Deck, &amp; Waterways</u>	<u>good</u>
		<u>Coal Bunkers, Openings, Lids, &amp;c.</u>	
		<u>Scuppers</u>	<u>good</u>
		<u>Cargo and Main Hatchways</u>	<u>good</u>
		<u>Hatches</u>	<u>good</u>

General Observations, Opinion as to Class, &c.

The bottom has been examined and coated. The pintles of the rudder rebushed.  
This vessel is in good and efficient condition and eligible in my opinion  
to remain as classed.

Committee's Minute FRIDAY 18 MAY 1883 18

Character assigned 100 A.1

J. H. Truscott  
Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

No.        Survey held at        Date, first Survey        Last Survey        18        
(No. of Visits       )

No. in Reg. Book. on the        Master         
Tonnage { Net        Built at        When built        Year.        Month.         
Gross        By whom built        Owners         
Under Dk.        Port belonging to        Destined Voyage         
If Surveyed Afloat or in Dry Dock         
(State Name of Dock.)

Last Survey, No.        Port of        Classed         
Years assigned.        Character in Register Book.

Present Condition of the			
Decks		<u>Treenails</u>	
Waterways		<u>Breasthooks and Stemson</u>	
Comings		<u>Transoms, Pointers, and Crutches</u>	
Upper Deck Beams & Fastenings		<u>Timbers of the Frame at the Openings</u>	
Lower Deck Beams & Fastenings		<u>Ditto ditto at other places</u>	
Planksheers		<u>Keelsons</u>	
Sheerstrakes		<u>Clamps and Shelves</u>	
Topsides		<u>Ceiling</u>	
Wales		<u>Rudder</u>	
Plank (Bottom) and Counter		<u>Copper or Y.M.</u>	<u>When put on</u>
Engine Room Skylights		<u>Caulking of</u>	
		<u>Bottom, Deck, &amp; Waterways</u>	
		<u>Coal Bunkers, Openings, Lids, &amp;c.</u>	
		<u>Scuppers</u>	
		<u>Cargo and Main Hatchways</u>	
		<u>Hatches</u>	

General Observations, Opinion as to Class, &c.

Committee's Minute        18      

Character assigned       

Surveyor to Lloyd's Register of British and Foreign Shipping.  
Certificate (if required, to be sent as per margin) Paid 18

Lon 670 -0279