

ANNUAL SURVEYS.

No. 205 Survey held at London Date, first Survey 10th April Last Survey 7th May 1883
 No. in Reg. Book. on the Iron Barque "Oriana" Master J. Pearce
 Tonnage 987 Net 1056 Gross 918 Under Dk. 918 Built at Greenock When built 1864 Year. 2nd Month. 2nd
 By whom built Scott & Co Owners Trinder, Anderson & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in Ratchiff Dry Dock
 (State Name of Dock.)

Last Survey, No. 41334 Port of London
 Present Condition of the
 Decks good Treennails good Rivets good
 Waterways Do Breasthooks and Stemson Do
 Comings Do Transoms, Pointers, and Crutches Do
 Upper Deck Beams & Fastenings Do Timbers of the Frame at the Openings Do
 Lower Deck Beams & Fastenings Do Ditto ditto at other places not seen
 Planksheers Do Keelsons good
 Sheerstrakes Do Clamps and Shelves Do
 Topsides Do Ceiling good
 Wales Do Rudder Do
 Plank (Bottom) and Counter Do Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. The rudder pintles rebashed. A few planks of deck refitted and a few renewed of yellow pine. The chain cables ranged and found complete. Vessel surveyed with part cargo in the hold amidsthips. She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 22 MAY 1883 18
 Character assigned J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 205 Survey held at London Date, first Survey 10th April Last Survey 7th May 1883
 No. in Reg. Book. on the Iron Barque "Oriana" Master J. Pearce
 Tonnage 987 Net 1056 Gross 918 Under Dk. 918 Built at Greenock When built 1864 Year. 2nd Month. 2nd
 By whom built Scott & Co Owners Trinder, Anderson & Co
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock in Ratchiff Dry Dock
 (State Name of Dock.)

Last Survey, No. 41334 Port of London Classed A.1
 Present Condition of the
 Decks good Treennails good Rivets good
 Waterways Do Breasthooks and Stemson Do
 Comings Do Transoms, Pointers, and Crutches Do
 Upper Deck Beams & Fastenings Do Timbers of the Frame at the Openings Do
 Lower Deck Beams & Fastenings Do Ditto ditto at other places not seen
 Planksheers Do Keelsons good
 Sheerstrakes Do Clamps and Shelves Do
 Topsides Do Ceiling good
 Wales Do Rudder Do
 Plank (Bottom) and Counter Do Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. The rudder pintles rebashed. A few planks of deck refitted and a few renewed of yellow pine. The chain cables ranged and found complete. Vessel surveyed with part cargo in the hold amidsthips. She is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 22 MAY 1883 18
 Character assigned J. H. Truscott.
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON670-0309