

ANNUAL SURVEYS.

42557

No. 23 Survey held at London Date, first Survey 2nd June Last Survey 2nd June 1883
No. in Reg. Book. on the Steel Sew. Lr. "Nanna". Master E. Olson.
Tonnage Net 351 Built at Gothenburg When built 1881 Month 11
Gross 454 Under Dk. 373 By whom built Motala Co Owners J. C. Giersten.
Port belonging to Bergen. Destined Voyage Blyth, thence to Riga.
If Surveyed Afloat or in Dry Dock In the Upper Globe Dry Dock.

Last Survey, No. 52 Port of Gothenburg
Present Condition of the
Decks good Treennails Rivets good
Waterways good Breasthooks and Stemson good
Comings good Transoms, Pointers, and Crutches good
Upper Deck Beams & Fastenings good Timbers of the Frame at the Openings good
Lower Deck Beams & Fastenings good Ditto ditto at other places not seen
Planksheers good Keelsons good
Sheerstrakes good Clamps and Shelves good
Topsides good Ceiling good
Wales good Rudder good
Plank (Bottom) and Counter good Copper or Y.M. When put on
Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
General Observations, Opinion as to Class, &c. The bottom has been examined and coated.
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 13 JUNE 1883 18 J. H. Truscott.
Character assigned 90A TRM Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Net Built at When built
Gross By whom built Owners
Under Dk. Destined Voyage
Port belonging to
If Surveyed Afloat or in Dry Dock (State Name of Dock.)
Last Survey, No. Port of Classed
Present Condition of the
Decks Treennails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

LON 670-0355