6/5/83

ANNUAL SURVEYS.

42561

(Received at London Office, ~~TUESDAY 29 MAY 1883~~)

No. _____ Survey held at London Date, first Survey 18 May Last Survey 18 May 1883 (No. of Visits _____)

No. in Reg. Book. 424 on the SS Glenlyon Master

Tonnage { Net 1373 Gross 2118 Under Dk. 2083 } Built at Glasgow When built Year. 1872 Month. 10

By whom built Sun & Glas bs Owners McGregor Sons & Co

Port belonging to Glasgow Destined Voyage China

If Surveyed Afloat or in Dry Dock Greens Dk (State Name of Dock.)

Last Survey, No. 41827 Port of Lon Classed | Years assigned. | Character in Register Book. 100A 9.82 SS Sun Mr 2.81.

Present Condition of the

Decks good | ~~Treenails~~ Rivets good | Windlass and Capstan good

Waterways " | Breasthooks and Stemson " | Pumps "

Comings " | Transoms, Pointers, and Crutches " | Boats "

Upper Deck Beams & Fastenings " | Timbers of the Frame at the Openings " | Masts, Yards, &c. "

Lower Deck Beams & Fastenings " | Ditto ditto at other places " | Condition, how ascertained From Dk

Planksheers " | Keelsons " | Sails good

Sheerstrakes " | Clamps and Shelfs " | Anchors, No. of 3 Bro. Dk & Reserve

Topsides " | Ceiling " | Cables Part on Dk good

Wales " | Rudder " | Hawsers and Warps "

Plank (Bottom) and Counter " | ~~Copper or Y.M.~~ Coated When put on now | Standing and Running Rigging "

Caulking of Bottom, Deck, & Waterways good

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c. Bottom be coated. She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 15 JUNE 1883 18

Character assigned 100A

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 ____

(If a Steam Ship, state if a report is also entered on the Machinery ...)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18 ____ (No. of Visits _____)

No. in Reg. Book. _____ on the _____ Master _____

Tonnage { Net _____ Gross _____ Under Dk. _____ } Built at _____ When built Year. _____ Month. _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed | Years assigned. | Character in Register Book.

Present Condition of the

Decks _____ | Treenails _____ | Windlass and Capstan _____

Waterways _____ | Breasthooks and Stemson _____ | Pumps _____

Comings _____ | Transoms, Pointers, and Crutches _____ | Boats _____

Upper Deck Beams & Fastenings _____ | Timbers of the Frame at the Openings _____ | Masts, Yards, &c. _____

Lower Deck Beams & Fastenings _____ | Ditto ditto at other places _____ | Condition, how ascertained _____

Planksheers _____ | Keelsons _____ | Sails _____

Sheerstrakes _____ | Clamps and Shelfs _____ | Anchors, No. of _____

Topsides _____ | Ceiling _____ | Cables _____

Wales _____ | Rudder _____ | Hawsers and Warps _____

Plank (Bottom) and Counter _____ | Copper or Y.M. _____ When put on _____ | Standing and Running Rigging _____

Caulking of Bottom, Deck, & Waterways _____

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18 ____

Character assigned _____

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18 ____

(Form ... 26/4/82.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

© 2021 Lloyd's Register Foundation

LON 670-0359