

16/83

ANNUAL SURVEYS.

42562

No. _____ Survey held at London Date, first Survey 21 May Last Survey SATURDAY 2 JUNE 1883
(Received at London on _____) (No. of Visits _____)
No. in on the SS Goorkha Master Sharp
Reg. Book. 4 Year. _____ Month. _____
Tonnage { Net 2660 Built at Sumbarton When built 1882
Gross 4104 By whom built W. Bennett & Co Owners Port Ind & N. Nav Co
Under Dk. 2612 Port belonging to Glasgow Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock albeit by SW & afloat
(State Name of Dock.) _____

Last Survey, No. 41876 Port of London Classed 100A-10.82
Years assigned. _____ Character in Register Book. _____

Present Condition of the			
Decks	<u>Good</u>	Treenails	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	<u>Good</u>
Planksheers	<u>Good</u>	Keelsons	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	<u>Good</u>
Topsides	<u>Good</u>	Ceiling	<u>Good</u>
Wales	<u>Good</u>	Rudder <u>Pruss Rivets</u>	<u>Good</u>
Plank (Bottom) and Counter	<u>Good</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Caulking of	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Bottom, Deck, & Waterways	<u>Good</u>
Scuppers	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Cargo and Main Hatchways	<u>Good</u>	Pumps	<u>Good</u>
Hatches	<u>Good</u>	Boats	<u>Good</u>
		Masts, Yards, &c.	<u>Good</u>
		Condition, how ascertained	<u>From SH</u>
		Sails	<u>Good</u>
		Anchors, No. of <u>4 Pns. SH & Reddy</u>	<u>Good</u>
		Cables <u>Part on SH</u>	<u>Good</u>
		Hawsers and Warps	<u>Good</u>
		Standing and Running Rigging	<u>Good</u>

General Observations, Opinion as to Class, &c. Bottom ke coated about 63 Pnats renewed in
after Red & Stampd. also several in the Rudder, & Rudder Pruss
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute FRIDAY 15 JUNE 1883 18 Senhouse Martindale
Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
(No. of Visits _____)
No. in on the _____ Master _____
Reg. Book. _____ Year. _____ Month. _____
Tonnage { Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Port belonging to _____ Destined Voyage _____
If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.) _____

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. _____ Character in Register Book. _____

Present Condition of the			
Decks		Treenails	
Waterways		Breasthooks and Stemson	
Comings		Transoms, Pointers, and Crutches	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings	
Lower Deck Beams & Fastenings		Ditto ditto at other places	
Planksheers		Keelsons	
Sheerstrakes		Clamps and Shelves	
Topsides		Ceiling	
Wales		Rudder	
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____	
Engine Room Skylights		Caulking of	
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	
Scuppers		Windlass and Capstan	
Cargo and Main Hatchways		Pumps	
Hatches		Boats	
		Masts, Yards, &c.	
		Condition, how ascertained	
		Sails	
		Anchors, No. of _____	
		Cables	
		Hawsers and Warps	
		Standing and Running Rigging	

General Observations, Opinion as to Class, &c. _____
Committee's Minute _____ 18
Character assigned _____
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) _____ Paid _____ 18

LONDON 70 - 0360

