

ANNUAL SURVEYS.

42597

MONDAY 11 JUNE 1883

No. Survey held at London Date, first Survey 4 June Last Survey 8 June 1883
(Received at London Office,)
No. in on the SS Ryhope Master Thomas Stewart
g. Book. 637 (No. of Visits)
Tonnage { Net 44.5 Built at Sunderland When built 1860
 { Gross 712 By whom built Laing Owners J. Tennant & Co.
 { Under Dk. 67.5 Port belonging to London Destined Voyage Coal Trade
If Surveyed Afloat or in Dry Dock Pontoon Victoria St
(State Name of Dock.)

Last Survey, No. 39919 Port of London

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Pine</u>	<u>Good</u>
Waterways	<u>Good</u>	Breasthooks and Stemson	<u>Good</u>	<u>Good</u>
Comings	<u>Good</u>	Transoms, Pointers, and Crutches	<u>Good</u>	<u>Good</u>
Upper Deck Beams & Fastenings	<u>Good</u>	Timbers of the Frame at the Openings	<u>Good</u>	<u>Good</u>
Lower Deck Beams & Fastenings	<u>Good</u>	Ditto ditto at other places	<u>Good</u>	<u>Good</u>
Plank-sheers	<u>Good</u>	Keelsons	<u>Good</u>	<u>Good</u>
Sheerstrakes	<u>Good</u>	Clamps and Shelves	<u>Good</u>	<u>Good</u>
Top-sides	<u>Good</u>	Ceiling	<u>Good</u>	<u>Good</u>
Bottom (Bottom) and Counter	<u>Good</u>	Rudder	<u>Good</u>	<u>Good</u>
Engine Room Skylights	<u>Good</u>	Copper or Y.M. <u>Boated</u> When put on <u>gun</u>	<u>Good</u>	<u>Good</u>
Coal Bunkers, Openings, Lids, &c.	<u>Good</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	<u>Good</u>
Scuppers	<u>Good</u>			
Cargo and Main Hatchways	<u>Good</u>			
Hatches	<u>Good</u>			

Classed A1 S.S. SS New No. 3.81
Years assigned. Character in Register Book.

Windlass and Capstan Good
Pumps Good
Boats Good
Masts, Yards, &c. Good
Condition, how ascertained Run & M
Sails Good
Anchors, No. of 4 Buoys, 12 Redys
Cables Part on boat
Hawsers and Warps Good
Standing and Running Rigging Good

(Insert Character precisely as in Register Book.)

Committee's Minute TUESDAY 26 JUNE 1883 18
Character assigned
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 1883

No. Survey held at Date, first Survey Last Survey 1883
(No. of Visits)
No. in on the Master
Reg. Book. (No. of Visits)
Tonnage { Net Built at When built
 { Gross By whom built Owners
 { Under Dk. Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Plank-sheers Keelsons
Sheerstrakes Clamps and Shelves
Top-sides Ceiling
Bottom (Bottom) and Counter Rudder
Engine Room Skylights Copper or Y.M. When put on
Coal Bunkers, Openings, Lids, &c. Caulking of Bottom, Deck, & Waterways
Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

(Insert Character precisely as in Register Book.)

Committee's Minute 1883
Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 1883

LON 670 20402

Ryhope

© 2021

Lloyd's Register
Foundation