

# ANNUAL SURVEYS.

42600

(Received at London Office, MONDAY 11 JUNE 1888)

No. 734 Survey held at London Date, first Survey 1 June Last Survey 1 June 1888  
 (No. of Visits \_\_\_\_\_)  
 No. in Reg. Book. on the SS British King Master Kelly  
 Tonnage { Net 2278 Built at Belfast When built 1881 Month. 1  
 Gross 3559  
 Under Dk. 3255 By whom built Harland Wolff & Owners Owners British Ship Owners  
 Port belonging to Liverpool Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Albert Dry Dock  
 (State Name of Dock.)

Last Survey, No. 28067 Port of Liv Classed 10047 6c 82  
 Years assigned. Character in Register Book.

Present Condition of the  
 Decks Good Treenails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "  
 Planksheers " Keelsons " Masts, Yards, &c. "  
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From Mr  
 Topsides " Ceiling " Sails Good  
 Wales " Rudder " Anchors, No. of 4 Nos. No. 8 Kedges  
 Plank (Bottom) and Counter " Copper or Y.M. Copper When put on run Cables Part on 1/2 Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. William & Co. const.  
She is now in an efficient state and eligible to remain as classed.

Committee's Minute TUESDAY 26 JUNE 1888 18 Senhouse Martindele  
 Character assigned TRW 100A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 (No. of Visits \_\_\_\_\_)  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Year. Month.  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
 (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Years assigned. Character in Register Book.  
 Present Condition of the  
 Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Republic.) (Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)



