

REPORT of SURVEY for REPAIRS, &c.

42635

(Received at Lloyd's Office, SATURDAY 7 JULY 1883)

No. in Reg. Book. 491 on the BE "Dumphail Castle" Date, first Survey 4th June Last Survey 4th July 1883
 Survey held at London (No. of Visits) Master A. Hilder
 TONNAGE under Tonnage Deck 644 Built at Sunderland When built 1861
 Ditto of Spar Deck, or Awning Deck
 Ditto of Poop
 Ditto of Raised Qr. Dk.
 Ditto of Houses on Deck
 Ditto of Forecastle
 Gross Tonnage 720 Owners J. H. Allan Residence
 Crew Space, as per Rule
 Register Tonnage, cut on Beam 720 By whom built J. Loring Destined Voyage Madras
 Engine Room
 Reg. Tons as St' mer, cut on Bm. If Surveyed Afloat or in Dry Dock Limetkiln dry dock (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Years assigned. Character in Register Book.
 Classed 16 A 1 6.82

Last Survey, No. 4627 Port Low Cause of Repairs to be clearly stated.
 REPAIRS, OR EXAMINATION AS PER RULE
 State dates of any letters respecting this case

Yellow metal stripped off, caulked from keel to gunwale and the bottom Resheathed with Yellow metal on keel

a Kedge Anchor 2. 1. 8 } now supplied Test 4. 17. 2 Lipton
2. 24 }

Public machine 12th Nov 1880 E. R. Sitt Suppt

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	<u>Good</u>
Waterways	<u>—</u>	Breasthooks and Stemson	<u>—</u>	Pumps	<u>2 No</u>
Comings	<u>—</u>	Transoms, Pointers, and Crutches	<u>—</u>	Boats	<u>4 No</u>
Upper Deck Beams & Fastenings	<u>—</u>	Timbers of the Frame at the openings	<u>—</u>	Masts, Yards, &c.	<u>—</u>
Lower Deck Beams & Fastenings	<u>—</u>	Ditto Ditto at other places	<u>Not seen</u>	Condition, how ascertained	<u>from Deck</u>
Planksheers	<u>—</u>	Keelsons	<u>—</u>	Sails	<u>Good</u>
Sheerstrakes	<u>—</u>	Clamps and Shelves	<u>—</u>	Anchor No. of	<u>3 B. 154 K</u>
Topsides	<u>—</u>	Ceiling	<u>—</u>	Cables	<u>part seen Good</u>
Wales	<u>—</u>	Rudder	<u>—</u>	Hawsers and Warps	<u>4 No</u>
Plank (Bottom) and Counter	<u>—</u>	Copper (or Y.M.) on Rudder When put on <u>Now</u> (State if on Felt.)	<u>—</u>	Standing & Running Rigging	<u>—</u>
Engine Room Skylights	<u>—</u>	Cement (if Iron Ship)	<u>—</u>	Cargo and Main Hatchways	<u>Good</u>
Coal Bunker, Openings, Lids, &c.	<u>—</u>	Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Hatches	<u>Good</u>
General Observations, Opinion as to Class, &c.	<u>Scuppers Good</u>				

She appears where seen in good condition and in my opinion eligible to continue as Classed

The Amount of Entry Fee ... £ 2 : 2 : — received by me, WVE
 9/7/83 Special ... £ 2 : 2 : — } 107 1883
 Certificate (if required) to be sent as per margin... } £ : 5 : —

Wm. C. Davy
 Surveyor to Lloyd's Register of British and Foreign Shipping.

TUESDAY 10 JULY 1883

Committee's Minute
 Character assigned

Class 11 A 1
WVE
10/7/83

