

ANNUAL SURVEYS.

42637

No. Survey held at London Date, first Survey 24 April Last Survey 3^d May 1883
 No. in Reg. Book. 233 on the SS Eldorado Master Stevenson
 Tonnage { Net 2157 Built at Hull When built 1873 Month. 3
 Gross 3332 By whom built Charles D Owners A Gray & J Harves
 Under Dk. 2128 Port belonging to Glasgow Destined Voyage Brisbane
 If Surveyed Afloat or in Dry Dock Albert Dry Dock & Afloat
 (State Name of Dock.)

Last Survey, No. 41811 Port of London

Classed 100 A 9.82
SS Lin W 2.81

Present Condition of the
 Decks Good Treennails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated. She is now in an efficient state and eligible to remain as classed

Committee's Minute

TUESDAY 10 JULY 1883 18

Character assigned

100 A 1

TRM

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage { Net Built at When built Year. Month.
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No.

Port of

Classed

Present Condition of the
 Decks Treennails
 Waterways Breasthooks and Stenson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.


Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

60670-0448