

# ANNUAL SURVEYS.

42661

No. 616 Survey held at London Date, first Survey and Last Survey 11 July 1885  
 No. in Reg. Book. on the Bk Prince Rupert Master Shaw  
 Tonnage { Net 491 Built at Pallion When built 1865 Month. 3  
 { Gross 491 By whom built W. Briggs & Co Owners Hudson's Bay Co  
 { Under Dk. 468 Port belonging to London Destined Voyage Vancouver's Island  
 If Surveyed Afloat or in Dry Dock Warehouse dry dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41524 Port of Lon  
 Present Condition of the Decks Good Treenails Good Classed 14A1 6.82  
 Waterways — Breasthooks and Stemson — Cont Lon Mar 79.945  
 Comings — Transoms, Pointers, and Crutches — Windlass and Capstan Good  
 Upper Deck Beams & Fastenings — Timbers of the Frame at the Openings — Pumps —  
 Lower Deck Beams & Fastenings — Ditto ditto at other places seen Boats 2 kw  
 Planksheers — Keelsons Good Masts, Yards, &c. —  
 Sheerstrakes — Clamps and Shelves — Condition, how ascertained from deck  
 Topsides — Ceiling — Sails Good  
 Wales — Rudder — Anchors, No. of 3 B. 1 S + 2 K  
 Plank (Bottom) and Counter std 1865 Copper or Y.M. mf When put on 6.82 Cables seen Good  
 Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c.  
Yellow metal patched where repaired. She appears as far as could be seen in good condition and eligible in my opinion to continue as classed

Committee's Minute TUESDAY 17 JULY 1885 Will L. Daavey  
 Character assigned Good Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
 No. in Reg. Book. on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 { Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 { Under Dk. \_\_\_\_\_ Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_ Treenails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-16/5/83.)  
 (If a Steam Ship, state if a Report is also sent on the Machinery...)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)  
 7670-0407

