

183

ANNUAL SURVEYS.

42662

No. 63 Survey held at London Date, first Survey 16 July Last Survey 24th July 18 83
(Received at London Office, 1. 8. 83)
No. in Reg. Book. on the BK Zamora Master A. Humming
(No. of Visits)
Tonnage Net 1180 Built at Dumbarton When built 1876 Year. 10 Month.
Gross 1218 By whom built Burrell & F Owners Scotia Ship Co
Under Dk. 1065 Port belonging to Glasgow Destined Voyage Brisbane
If Surveyed Afloat or in Dry Dock Greens Dock Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 28163 Port of Liv
Present Condition of the
Decks good Treenails Rivets good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Canted When put on new
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "
General Observations, Opinion as to Class, &c. Bottom & counter.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday AUGUST, 3rd 83. Senhouse Martindale
Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 537 Survey held at London Date, first Survey 18 July Last Survey 19 July 18 83
(Received at London Office, 1. 8. 83)
No. in Reg. Book. on the S Loch Awe Master A. Nicoll
(No. of Visits)
Tonnage Net 1053 Built at Glasgow When built 1889 Year. 4 Month.
Gross 1101 By whom built Barday & Co Owners J & R Wilson
Under Dk. 1000 Port belonging to Glasgow Destined Voyage Barra
If Surveyed Afloat or in Dry Dock Pontine Victoria St Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 28163 Port of Liv
Present Condition of the
Decks good Treenails Rivets good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder brushed
Plank (Bottom) and Counter " Copper or Y.M. Canted When put on new
Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches "
General Observations, Opinion as to Class, &c. Bottom & counter & Rudder brushed.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute Friday AUGUST, 3rd 83. Senhouse Martindale
Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs, 4000-18/5/83.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.)
(If a steam ship, etc.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

Low 670-0498