

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey 25 June Last Survey 29 June 1883

No. in on the Reg. Book. 1095 Master J. Simons
 Tonnage { Net 1491 Built at Newcastle When built 1880 10
 Gross 2258
 Under Dk. 2154 By whom built A Leslie & Co Owners W. Milburn & Co

Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock James & W. Sykes & afloat
 (State Name of Dock.)

Last Survey, No. 330 Port of Cal Classed 100A 1.23

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c coated, New Propeller.
She is now in an efficient state
and eligible to remain as classed.

Committee's Minute TUESDAY 17 JULY 1883 18 Senhouse Martinade
 Character assigned 100A 1.23 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in on the Reg. Book. Master
 Tonnage { Net Built at When built
 Gross
 Under Dk. By whom built Owners

Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Common
very rare