

ANNUAL SURVEYS.

42669

No. Survey held at London Date, first Survey 12 July Last Survey 19 July 1883
(Received at London Office MONDAY 23 JULY 1883)
 No. in Reg. Book. on the SS Glencoe Master W Gulland
(No. of Visits)
378 Tonnage Net 1901 Gross 2913 Under Dk. 2685 Built at Glasgow When built 1878 Year. Month.
 By whom built Lon & Glas Co Owners M Gregor Gow &
 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Greens Bay St Raphael
(State Name of Dock.)

Last Survey, No. 42175 Port of London
 Present Condition of the
 Decks Good Treenails Good Rivets Good
 Waterways Good Breasthooks and Stenson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Covered When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. Bottom & covered
She is now in an efficient state & eligible to remain as classed

Committee's Minute Friday AUGUST 3rd 1883.
 Character assigned TBW 100A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
 No. in Reg. Book. on the Master
Year. Month.
 Tonnage Net Built at When built
Gross By whom built Owners
Under Dk.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stenson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)

