

Report of Survey for Repairs of Engines and Boilers.

No. 102
No. in Reg. Book. 52
Survey held at London
Date, first Survey 4 July
Last Survey 11 July 1883
on the Machinery of the S. S. Athyros.
(Number of Visits 3)

Tonnage, Gross 1398
Ditto, Net 1069
Diameter of Cylinder 31 54
Length of Stroke 33
Pressure of Steam 61
Registered Horse Power 130
Built at Glasgow
Owners Globe Steam S. Co.
Engines made by London & Glasg Co.
Boilers made by
If Surveyed Afloat or in Dry Dock Pontons.
(State name of Dock.)
When built 1871
Port belonging to London
When made 1871
When made 1871
Classed 100A1
Years assigned 10 82
Character in Register Book.
B & M S. 8.82

Particulars of Repairs and Examination Broken Stern Frame
(State cause of Repairs.)
Examined Seacocks & connections & found them in a good condition. The stern tube and shaft have been drawn & replaced. The tips of the propeller blades have been cut off reducing the total surface to about 36 ft.

General Observations, Opinion, and Recommendation:—As far as seen the machinery of this vessel is now in a safe working condition and is in my opinion eligible to remain as classed.

Entry or Registering Fee... £ : :
Survey Fee (per Section 28) ... £ : :
Certificate (if required) ... £ : :
to be sent as per margin.
(Travelling Expenses, if any, £)

Committee's Minute TUESDAY 24 JULY 1883 188
Assigned

W. Stornley
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

It is submitted that this vessel is
eligible to remain as blessed.

D. G.

19/7/83.



© 2021

Lloyd's Register
Foundation