

ANNUAL SURVEYS.

42720
31.7.83

No. Survey held at London Date, first Survey 20th July Last Survey 23rd July 1883
 No. in Reg. Book. on the Iron Screw S. "Eeta." Master T. Richards.
 Tonnage Net 765 Built at Newcastle When built 1882 Month. 3rd
Gross 1191 By whom built W. Richardson & Co Owners Demerara & Berbice Str. Shipp. Co.
Under Dk. 878 Port belonging to London Destined Voyage
 If Surveyed Afloat or in Dry Dock In the Bridge Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 16778 Port of Swice Classed 100 A.1.
 Present Condition of the
 Decks good Rivets good
 Waterways D^o Breasthooks and Stemson D^o
 Comings D^o Transoms, Pointers, and Crutches D^o
 Upper Deck Beams & Fastenings D^o Timbers of the Frame at the Openings D^o
 Lower Deck Beams & Fastenings D^o Ditto ditto at other places not seen
 Planksheers D^o Keelsons good
 Sheerstrakes D^o Clamps and Shelves
 Topsides D^o Ceiling D^o
 Wales D^o Rudder D^o
 Plank (Bottom) and Counter D^o Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps D^o
 Boats D^o
 Masts, Yards, &c. D^o
 Condition, how ascertained from the deck
 Sails good
 Anchors, No. of 3 B. 1 P. 2 K.
 Cables good
 Hawsers and Warps D^o
 Standing and Running Rigging D^o
 Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated.
This vessel is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 17 AUGUST 1883
 Character assigned 100 A.1
 J. H. Truscott
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Net Built at When built
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Windlass and Capstan
 Pumps
 Boats
 Masts, Yards, &c.
 Condition, how ascertained
 Sails
 Anchors, No. of
 Cables
 Hawsers and Warps
 Standing and Running Rigging
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

LONB70-0596

