

ANNUAL SURVEYS.

No. 378 Survey held at London Date, first Survey 3 August Last Survey 3 August 1883
 No. in Reg. Book. 378 on the S Piacco Master Proy
 Tonnage Net 1075 Built at Glasgow When built 1876 Month. 12
 Gross 1136 By whom built A Stephen & Co Owners New Zealand Shipping Co
 Under Dk. 982 Port belonging to Sydney Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Albert Dry Dock
 (State Name of Dock.)

Last Survey, No. 41706 Port of London
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ Corked When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c. coated.
She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 17 AUGUST 1883 18
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 23 Survey held at London Date, first Survey 3 July Last Survey 25 July 1883
 No. in Reg. Book. 23 on the S Mac Callum More Master A Smith
 Tonnage Net 1667 Built at Glasgow When built 1873 Month. 11
 Gross 1740 By whom built A Beaman Owners J B Campbell
 Under Dk. 1572 Port belonging to London Destined Voyage Australia
 If Surveyed Afloat or in Dry Dock Green St & afloat
 (State Name of Dock.)

Last Survey, No. 5766 Port of London
 Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " ~~Copper or Y.M.~~ Corked When put on now
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom &c. coated.
She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 17 AUGUST 1883 18
 Character assigned 100A1
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Lon 670 - 0601

