

ANNUAL SURVEYS.

42729

No. 1215 Survey held at London Date, first Survey 1 August 1883 (Received at London Office TUESDAY 11 AUGUST 1883)
 No. in Reg. Book. on the SS Aurora Master _____ (No. of Visits _____)
 Tonnage 446 Net Built at Newcastle When built 1863 Year. 6 Month. _____
711 Gross By whom built Palmer & Co Owners London Steam Ship Co
646 Under Dk. Port belonging to London Destined Voyage Mediterranean
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St Society's Freeboard (if assigned) as painted on Ship
(State Name of Dock.)

Last Survey, No. 41642 Port of London Classed 95A-782
Years assigned. Character in Register Book.
SS Aurora 1880

Present Condition of the Decks <u>good</u>	Treenails <u>Pivots</u> <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>from SH</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3 No. 12 & 8 No. 10</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Part on SH</u> <u>good</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>new</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Cargo and Main Hatchways <u>good</u>
Coal Bunkers, Openings, Lids, &c. <u>good</u>	Scuppers <u>good</u>	Hatches <u>"</u>

She is now in an efficient state and eligible to remain as classed.

Samhouse Martindale

FRIDAY 17 AUGUST 1883

Committee's Minute _____
 Character assigned 95A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
(No. of Visits _____)
 No. in Reg. Book. on the _____ Master _____ Year. _____ Month. _____
 Tonnage Net _____ Built at _____ When built _____
Gross _____ By whom built _____ Owners _____
Under Dk. _____ Destined Voyage _____
 Port belonging to _____ Society's Freeboard (if assigned) as painted on Ship _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

Committee's Minute _____
 Character assigned _____ Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) _____ Paid _____ 18 _____



Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

Lomb70-0605

