

# REPORT of SURVEY for REPAIRS, &c.

42744  
16/8/83

No. in Survey held at London Date, first Survey 2<sup>nd</sup> July Last Survey 13<sup>th</sup> August 1883  
 Reg. Book. on the SS Sikh Master Johnson  
 (Received at London Office, (No. of Visit))

TONNAGE under Tonnage Deck 2180  
 Ditto of Spar Deck, or Avning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 2308  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as St' mer, cut on Bm. 1510  
 Built at Glasgow When built 1880 YEAR. MONTH. 11  
 Owners Gallatley, Hankley & Co Port belonging to Glasgow  
 Residence  
 By whom built Aitken & Manue Destined Voyage  
 If Surveyed Afloat or in Dry Dock Albert by St. Vaston  
 (State Name of Dock)

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
 Classified 100A-1.83  
 Years assigned. Character in Register Book.

Last Survey, No. 42225 Port London  
 REPAIRS, OR EXAMINATION AS PER RULE  
 Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship 5ft 9in Salt Water only  
 State dates of any letters respecting this case

*I visited this vessel the day before she sailed and they had only painted the freeboard for salt water & L. R. attached.*

*not the bars for fresh water the same there this is not of importance*



Present Condition of the	Good	Bad	Good	Good
Decks	Good	Treenails Rivets	Good	Windlass and Capstan
Waterways	"	Breasthooks and Stemson	"	Pumps
Comings	"	Transoms, Pointers, and Crutches	"	Boats
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained
Planksheers	"	Keelsons	"	Sails
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <u>3 Bro. St &amp; Kedy</u>
Topsides	"	Ceiling	"	Cables <u>Part on St</u>
Wales	"	Rudder	"	Hawsers and Warps
Plank (Bottom) and Counter	"	Copper (or Y.M.) <u>Good</u> When put on <u>new</u> (State if on Felt.)	"	Standing & Running Rigging
Engine Room Skylights	Good	Cement (if Iron Ship)	Good	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	"	Hatches
General Observations, Opinion as to Class, &c.	<u>Bottom be coated</u> <u>She is now in an efficient state and eligible to remain as classed.</u>			

The Amount of Entry Fee ... £ : : received by me, }  
 Special ... £ : : 188 }  
 Certificate (if required) } £ : :  
 to be sent as per margin... }  
 (Travelling Expenses, if any, £ )  
 Committee's Minute  
 Character assigned

*Senhouse Martindale*  
 Surveyor to Lloyd's Register of British and Foreign Shipping.

TUESDAY 21<sup>st</sup> AUGUST 1883

*10071*  
*Notefield*



© 2021  
 Lloyd's Register  
 Foundation  
 LON 670 208 211

Insert Character precisely as in Register Book.