

ANNUAL SURVEYS.

No. 312 Survey held at London Date, first Survey 10 Aug 1883 Last Survey 17 Aug 1883
No. in Reg. Book. on the SS John M. Intyre Master J Johnston
Tonnage Net 630 Gross 221 Under Dk. 525 Built at Newcastle When built 1863
By whom built Palmers Owners J Fenwick & Co
Port belonging to London Destined Voyage Tyne Collier
If Surveyed Afloat or in Dry Dock Canton Victoria Dk Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed 30th 8.82
Present Condition of the SS John M. 3.80
Decks Good Treenails Rivets Good
Waterways " Breasthooks and Stemson "
Comings " Transoms, Pointers, and Crutches "
Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
Lower Deck Beams & Fastenings " Ditto ditto at other places "
Planksheers " Keelsons "
Sheerstrakes " Clamps and Shelves "
Topsides " Ceiling "
Wales " Rudder "
Plank (Bottom) and Counter " Copper or Y.M. Bouted When put on now
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
General Observations, Opinion as to Class, &c. Bottom be coated
She is now in an efficient state and eligible to remain as classed.

Committee's Minute 4 SEPTEMBER 1883
Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
No. in Reg. Book. on the Master
Tonnage Net Built at When built
Gross By whom built Owners
Under Dk.
Port belonging to Destined Voyage
If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship
Last Survey, No. Port of Classed
Present Condition of the
Decks Treenails
Waterways Breasthooks and Stemson
Comings Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
Lower Deck Beams & Fastenings Ditto ditto at other places
Planksheers Keelsons
Sheerstrakes Clamps and Shelves
Topsides Ceiling
Wales Rudder
Plank (Bottom) and Counter Copper or Y.M. When put on
Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
General Observations, Opinion as to Class, &c.

Committee's Minute
Character assigned 4 SEPTEMBER 1883
Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

ANNUAL SURVEYS.

Wm M. M. M.

[Faint, mostly illegible text and handwriting, possibly bleed-through from the reverse side of the page.]