

ANNUAL SURVEYS.

42818
6.8.83

No. 364 Survey held at Louaou Date, first Survey Sept 26 Last Survey Sept 4 1883
 Reg. Book. on the GLENNARTNEY Iron Screw Steamer Master Wallace
 Tonnage 1400 Net Built at Glasgow When built 1873 Year. Month.
2143 Gross Under Dk. 2065 By whom built Lou & Glas Ship & Co Owners McGregor & Co
 Port belonging to Louaou Destined Voyage China
 If Surveyed Afloat or in Dry Dock Drown's Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 142347 Port of Louaou 3-83 Classed 100.A.23
 Present Condition of the Decks Good Treenails Good Years assigned. Character in Register Book.
SS Lon No. 82

Waterways	Breasthooks and Stemson	Windlass and Capstan <u>Good</u>
Comings	Transoms, Pointers, and Crutches	Pumps <u>3</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Boats <u>5</u>
Lower Deck Beams & Fastenings	Ditto ditto at other places <u>Good</u>	Masts, Yards, &c.
Planksheers	Keelsons	Condition, how ascertained <u>from deck</u>
Sheerstrakes	Clamps and Shelves	Sails <u>2 Suits</u>
Topsides	Ceiling	Anchors, No. of <u>3 B-1 S-2 K</u>
Wales	Rudder	Cables <u>when seen</u> <u>Good</u>
Plank (Bottom) and Counter	Copper or Y.M. <u>Cement</u> When put on <u>3</u>	Hawsers and Warps
Engine Room Skylights <u>good</u>	Caulking of Bottom, Deck, & Waterways <u>good</u>	Standing and Running Rigging

General Observations, Opinion as to Class, &c. This vessel seen in dry dock bottom examined scraped & painted. covering strap out on but of Rudder plate on port side & 2 loose rivets in frame. Stern frame examined & 2 loose rivets in bridge aperture. She appears in sound & efficient condition & eligible in my opinion to continue as classed

Committee's Minute TUESDAY 11 SEPT 1883
 Character assigned 100 J.W. Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 Reg. Book. on the _____ Master _____
 Tonnage Net _____ Built at _____ When built _____ Year. Month.
Gross _____ Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____ Years assigned. Character in Register Book.
 Waterways _____ Breasthooks and Stemson _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Plank (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid _____ 18____

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (If a Steam Ship, state if a Report is also sent on the Machinery)

(Insert Character precisely as in Register Book.)
 9900-1E9N07

