

ANNUAL SURVEYS.

(Received at London Office, 4/28/83)

No. 392 Survey held at London Date, first Survey 22 Aug Last Survey 24 August 1883
 No. in Reg. Book. on the SS Gleneagles Master K Gasson
 Tonnage 1838 Built at Glasgow When built 1877
2758 By whom built Sen & Glas Owners M Gregor Gow
 Under Dk. 2577 Port belonging to Glasgow Destined Voyage China
 If Surveyed Afloat or in Dry Dock Green St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 42043 Port of Don

Classed 100 A 12.82

SS Sen No 1.81.

Present Condition of the	Treenails <u>Rivets</u>	Windlass and Capstan <u>Good</u>
Decks <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>Good</u>
Waterways <u>Good</u>	Transoms, Pointers, and Crutches <u>Good</u>	Boats <u>Good</u>
Comings <u>Good</u>	Timbers of the Frame at the Openings <u>Good</u>	Masts, Yards, &c. <u>Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Ditto ditto at other places <u>Good</u>	Condition, how ascertained <u>From St</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails <u>Good</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>Good</u>	Anchors, No. of <u>3 Bros. 12 & 14 lbs</u>
Sheerstrakes <u>Good</u>	Ceiling <u>Good</u>	Cables <u>Part on 1/2</u>
Topsides <u>Good</u>	Rudder <u>Good</u>	Hawsers and Warps <u>Good</u>
Wales <u>Good</u>	Copper or Y.M. <u>Copper</u> When put on <u>new</u>	Standing and Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u>
Engine Room Skylights <u>Good</u>	Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Hatches <u>Good</u>
General Observations, Opinion as to Class, &c.	Scuppers <u>Good</u>	

Bottom in contact.
She is now in an efficient state
and eligible to remain as classed.

Senhouse Martindale

Committee's Minute TUESDAY 11 SEPT 1883

Character assigned 100 A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18

No. in Reg. Book. on the Master Year. Month.

Tonnage Built at When built
 By whom built Owners

Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of

Classed


Present Condition of the	Treenails	Windlass and Capstan
Decks	Breasthooks and Stemson	Pumps
Waterways	Transoms, Pointers, and Crutches	Boats
Comings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Upper Deck Beams & Fastenings	Ditto ditto at other places	Condition, how ascertained
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors, No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper or Y.M. When put on	Standing and Running Rigging
Plank (Bottom) and Counter	Caulking of Bottom, Deck, & Waterways	Cargo and Main Hatchways
Engine Room Skylights	Coal Bunkers, Openings, Lids, &c.	Hatches
General Observations, Opinion as to Class, &c.	Scuppers	

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

2500-1-1007