

ANNUAL SURVEYS.

42833
FRIDAY 7 SEPT 1883

No. 162 Survey held at London Date, first Survey 6 July Last Survey 31 July 1883
 Reg. Book. on the SS Howarden Castle Master _____
 Tonnage { Net 2722 Built at Glasgow When built 1883 Month. 1
 Gross 4241 By whom built J Elder Owners S Currie & Co
 Under Dk. 4012 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship _____
 (State Name of Dock.)

Last Survey, No. 42468 Port of London

Classed 100 Years assigned. 4.83 Character in Register Book.

Present Condition of the

Decks Good

Waterways "

Comings "

Upper Deck Beams & Fastenings "

Lower Deck Beams & Fastenings "

Planksheers "

Sheerstrakes "

Topsides "

Wales "

Plank (Bottom) and Counter "

Engine Room Skylights Good

General Observations, Opinion as to Class, &c.

Treenails Good

Breasthooks and Stemson "

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings "

Ditto ditto at other places "

Keelsons "

Clamps and Shelves "

Ceiling "

Rudder "

Copper or Y.M. Copper When put on Now

Caulking of Good

Bottom, Deck, & Waterways Good

Windlass and Capstan Good

Pumps "

Boats "

Masts, Yards, &c. "

Condition, how ascertained From M

Sails Good

Anchors, No. of 4 Bbs 12 & 14

Cables Cable on the Good

Hawsers and Warps "

Standing and Running Rigging "

Cargo and Main Hatchways Good

Hatches "

Bottom & counter,
and eligible to remain as classed.

Leahouse Markham

Committee's Minute

FRIDAY 14 SEPT 1883

Character assigned

100

JW

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18

Reg. Book. on the _____ Master _____ (No. of Visits _____)

Tonnage { Net _____ Built at _____ When built _____ Year. _____ Month. _____

Gross _____ By whom built _____ Owners _____

Under Dk. _____ Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship _____

(State Name of Dock.)

Last Survey, No. _____ Port of _____

Classed _____ Years assigned. _____ Character in Register Book.

Present Condition of the

Decks _____

Waterways _____

Comings _____

Upper Deck Beams & Fastenings _____

Lower Deck Beams & Fastenings _____

Planksheers _____

Sheerstrakes _____

Topsides _____

Wales _____

Plank (Bottom) and Counter _____

Engine Room Skylights _____

General Observations, Opinion as to Class, &c.

Treenails _____

Breasthooks and Stemson _____

Transoms, Pointers, and Crutches _____

Timbers of the Frame at the Openings _____

Ditto ditto at other places _____

Keelsons _____

Clamps and Shelves _____

Ceiling _____

Rudder _____

Copper or Y.M. _____ When put on _____

Caulking of _____

Bottom, Deck, & Waterways _____

Windlass and Capstan _____

Pumps _____

Boats _____

Masts, Yards, &c. _____

Condition, how ascertained _____

Sails _____

Anchors, No. of _____

Cables _____

Hawsers and Warps _____

Standing and Running Rigging _____

Cargo and Main Hatchways _____

Hatches _____

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

(If a Steam Ship, state if a Report is also sent on the Machinery)

(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/83.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

LONG 1-0083