

ANNUAL SURVEYS.

No. 451 Survey held at London Date, first Survey July 12 Last Survey July 12 1883
 No. in Reg. Book. on the Iron S. S. Lisbon Master J. E. Hall
 Tonnage { Net 860 Built at Nest Hartlepool When built 1871
 Gross 1334 By whom built Denton Gray & Co Owners J. Hall junr & Co
 Under Dk. 1294 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Regent Dry Dock Society's Freeboard (if assigned) as painted on Ship _____
 (State Name of Dock.)

Last Survey, No. 41954 Port of London Classed S. S. Lou N° 3-82 Character in Register Book. 100 A 1
 Present Condition of the Decks Good Treenails Good Breasthooks and Stemson Good Windlass and Capstan Good
 Waterways Good Transoms, Pointers, and Crutches Good Pumps Good
 Comings Good Timbers of the Frame at the Openings Good Boats Good
 Upper Deck Beams & Fastenings Good Ditto ditto at other places Good Masts, Yards, &c. Good
 Lower Deck Beams & Fastenings Good Keelsons Good Condition, how ascertained by observation
 Planksheers Good Clamps and Shelves Good Sails Sufficient
 Sheerstrakes Good Ceiling Good Anchors, No. of 3 B 1 S & 2 K
 Topsides Good Rudder Good Cables Sufficient
 Wales Good Copper or Y.M. Plated When put on 1871 Hawfers and Warps Sufficient
 Plank (Bottom) and Counter Good Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock the bottom examined and recoated with Paint, is in good and efficient condition and eligible in my opinion to remain as classed.

Committee's Minute TUESDAY 18 SEPT 1883 Surveyor to Lloyd's Register of British and Foreign Shipping. J. W. Miles
 Character assigned 100 A 1 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18
 No. in Reg. Book. on the _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____ Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____ Society's Freeboard (if assigned) as painted on Ship _____
 (State Name of Dock.)
 Last Survey, No. _____ Port of _____ Classed _____
 Present Condition of the Decks _____ Treenails _____ Breasthooks and Stemson _____ Windlass and Capstan _____
 Waterways _____ Transoms, Pointers, and Crutches _____ Pumps _____
 Comings _____ Timbers of the Frame at the Openings _____ Boats _____
 Upper Deck Beams & Fastenings _____ Ditto ditto at other places _____ Masts, Yards, &c. _____
 Lower Deck Beams & Fastenings _____ Keelsons _____ Condition, how ascertained _____
 Planksheers _____ Clamps and Shelves _____ Sails _____
 Sheerstrakes _____ Ceiling _____ Anchors, No. of _____
 Topsides _____ Rudder _____ Cables _____
 Wales _____ Copper or Y.M. _____ When put on _____ Hawfers and Warps _____
 Plank (Bottom) and Counter _____ Caulking of Bottom, Deck, & Waterways _____ Standing and Running Rigging _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____
 General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Character assigned _____ Certificate (if required, to be sent as per margin) Paid 18