

ANNUAL SURVEYS.

42878

(Received at London Office, TUESDAY 10 SEPT 1883)

No. 285 Survey held at London Date, first Survey 12 Sept Last Survey 13 Sept 1883
No. in Reg. Book. on the SS Asian Master J. Raison
Net 1211 Built at Newcastle When built 1876 Year. 9 Month. 9
Gross 1869 By whom built C. S. Swan Owners Glover Bros
Under Dk. 1792 Port belonging to London Destined Voyage Cardiff
If Surveyed Afloat or in Dry Dock Greens St Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 2955 Port of Bel. Classed 100 A 1 5.83
Present Condition of the Decks Good Treenails Rivets Good
Waterways 11 Breasthooks and Stemson 11
Comings 11 Transoms, Pointers, and Crutches 11
Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11
Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11
Planksheers 4 Keelsons 11
Sheerstrakes 11 Clamps and Shelves 11
Topsides 11 Ceiling 11
Wales 11 Rudder 11
Plank (Bottom) and Counter 4 Copper or Y.M. Coated When put on now
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches 11
General Observations, Opinion as to Class, &c. Bottom is coated
She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 21 SEPT 1883
Character assigned 100 A 1 JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

No. 285 Survey held at London Date, first Survey 12 Sept Last Survey 13 Sept 1883
No. in Reg. Book. on the SS Asian Master J. Raison
Net 1211 Built at Newcastle When built 1876 Year. 9 Month. 9
Gross 1869 By whom built C. S. Swan Owners Glover Bros
Under Dk. 1792 Port belonging to London Destined Voyage Cardiff
If Surveyed Afloat or in Dry Dock Greens St Society's Freeboard (if assigned) as painted on Ship
Last Survey, No. 2955 Port of Bel. Classed 100 A 1 5.83
Present Condition of the Decks Good Treenails Rivets Good
Waterways 11 Breasthooks and Stemson 11
Comings 11 Transoms, Pointers, and Crutches 11
Upper Deck Beams & Fastenings 11 Timbers of the Frame at the Openings 11
Lower Deck Beams & Fastenings 11 Ditto ditto at other places 11
Planksheers 4 Keelsons 11
Sheerstrakes 11 Clamps and Shelves 11
Topsides 11 Ceiling 11
Wales 11 Rudder 11
Plank (Bottom) and Counter 4 Copper or Y.M. Coated When put on now
Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches 11
General Observations, Opinion as to Class, &c. Bottom is coated
She is now in an efficient state and eligible to remain as classed.

Committee's Minute FRIDAY 21 SEPT 1883
Character assigned 100 A 1 JTBW Surveyor to Lloyd's Register of British and Foreign Shipping.
Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 4000-18/5/83.)
(If a Steam Ship, state if a Report is also sent on the alterations.)
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)



