

Report of Survey for Repairs of Engines and Boilers.

428807

No. _____ (Received at London Office, FRIDAY 21 SEPT 1883)

No. in Reg. Book. *571* Survey held at *London* Date, first Survey *23 July* Last Survey *29 Aug* 188*3*

on the Machinery of the *S. P. Shoreham* (Number of Visits *5*)

Tonnage, Gross <i>491</i>	Built at <i>Port Glasgow</i>	When built <i>1872</i>
Ditto, Net <i>293</i>	Owners <i>S. Clarke & Co</i>	Port belonging to <i>London</i>
Diameter of Cylinder <i>24 42</i>	Engines made by <i>Walker Henderson & Co</i>	When made <i>1872</i>
Length of Stroke <i>30</i>	Boilers made by _____	When made <i>1879</i>
Pressure of Steam <i>60</i>	If Surveyed Afloat or in Dry Dock <i>Thames Iron Works</i>	Classed <i>90 A1</i>
Registered Horse Power <i>80</i>	(State name of Dock.)	Years assigned <i>5 82</i>
Last Survey No. _____	Port _____	<i>L.M.C. 281. B.S. 12.82.</i>

Particulars of Repairs and Examination *Annual*

(State cause of Repairs.)

Examined sea-cocks & connections & found them in a good condition. The lignum vitae in stern tube has been renewed.

A new donkey boiler has been fitted by Mr R White of Millwall. No opportunity was afforded me of examining or testing it. The owners representative said it would be submitted for inspection on the Tyne where the vessel is now trading. The Newcastle Surveyors have been informed of the case & and the particulars (as far as ^{they} could be ascertained) have been forwarded to them.

General Observations, Opinion, and Recommendation:— *As far as seen the machinery of this vessel appears to be in a safe working condition and provided the report on the donkey boiler is satisfactory the vessel appears in my opinion to be eligible to remain as classed.*

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : received by me,
 Certificate (if required) ... £ : : 188
 to be sent as per margin.
 (Travelling Expenses, if any, £)

C. D. Stromeier
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

TUESDAY 25 SEPT 1883 188

Assigned



© 2021

Lloyd's Register Foundation

(State of the port is also sent on the Hall of the Ship
 Condition of Engines and Boilers, and subsequent repairs and examinations, to be clearly stated.)

Insert Character precisely as in the Register Book.

0510-1E9M07

