

ANNUAL SURVEYS.

43007

No. 383 Survey held at London Date, first Survey August 1st Last Survey August 1st 1883
 No. in Reg. Book. on the Iron S.S. "Glendale" Master Henderson
 Tonnage 1127 Built at West Hartlepool When built 1874
 By whom built R. Irvine & Co Owners Steel Young & Co
 Port belonging to West Hartlepool Destined Voyage Constantinople
 If Surveyed Afloat or in Dry Dock West India Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. 41743 Port of London Classed S.S. class 2-82 Character in Register Book. 90 A 1

Present Condition of the
 Decks Good Treenails Good Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons where seen
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1874
 Caulking of Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good

General Observations, Opinion as to Class, &c. This vessel has now been placed in Dry Dock, the bottom examined and recoated with paint, and new life Boat put on board instead of one damaged. Hatches part new. She is now in good and efficient condition and eligible in my opinion to remain as classed.


Committee's Minute TUESDAY 2 OCTOBER 1883
 Character assigned 90 A 1 Surveyor to Lloyd's Register of British and Foreign Shipping. J. W. Miles
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock Society's Freeboard (if assigned) as painted on Ship

Last Survey, No. Port of Classed

Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stenson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



© 2021

Lloyd's Register Foundation

610-14907