

ANNUAL SURVEYS.

43074
THURSDAY 4 OCT 1883

No. 307 Survey held at London Date, first Survey Sept 29 Last Survey Sept 29 1883
 No. in Reg. Book. on the Iron Sailing Ship PERSIAN Master Black
 Tonnage Net 1387 Built at Glasgow When built 1878 5
 Gross 1452 Under Dk. 1324 By whom built Scott & Co Owners L. S. Clark

Port belonging to London Destined Voyage Sydney
 If Surveyed ~~Afloat~~ in Dry Dock Dept. of Green Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.) London Dry Dock

Last Survey, No. 3550 Port of Whin Brew Classed 100A1
 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Quits where seen</u>	<u>Good</u>	SS Bow No. 1-82	<u>10-82</u>	
Waterways		Breasthooks and Stenson			Windlass and Capstan	<u>Good</u>	
Comings		Transoms, Pointers, and Crutches			Pumps	<u>3</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			Boats	<u>4</u>	
Lower Deck Beams & Fastenings		Ditto ditto at other places			Masts, Yards, &c.		
Planksheers		Keelsons			Condition, how ascertained	<u>from deck</u>	
Sheerstrakes		Clamps and Shelves			Sails	<u>what seen</u> <u>good</u>	
Topsides		Ceiling			Anchors, No. of	<u>3 B - 1 S - 2 K</u>	
Wales		Rudder			Cables	<u>what seen</u> <u>good</u>	
Plank (Bottom) and Counter		Copper or Y.M. Cement When put on			Hawsers and Warps		
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways			Standing and Running Rigging		
Coal Bunkers, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	Cargo and Main Hatchways	<u>good</u>	Hatches	<u>4</u>

General Observations, Opinion as to Class, &c.
This vessel was placed in dry dock for owners Survey for change of ownership lower Rudder post bushed, bottom examined scraped & painted. She appears in a sound & efficient condition and eligible in my opinion to continue as classed.

Committee's Minute FRIDAY 5 OCT 1883
 Character assigned T.W. 100A1
 Edward John Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 612 Survey held at London Date, first Survey Oct 2nd Last Survey Oct 3rd 1883
 No. in Reg. Book. on the Iron Sailing Barque WATAURA Master Greenstreet
 Tonnage Net 853 Built at Glasgow When built 1868 - 12
 Gross 898 Under Dk. 84 1/2 By whom built Arthur Manuel Owners New Zealand Ship Co.

Port belonging to Littleton New Zealand Destined Voyage New Zealand
 If Surveyed ~~Afloat~~ in Dry Dock Banau Dry Dk. Society's Freeboard (if assigned) as painted on Ship
 (State Name of Dock.)

Last Survey, No. 41938 Port of Son Classed #. A.1.
 Years assigned. Character in Register Book.

Present Condition of the Decks	<u>Good</u>	Treenails	<u>Quits where seen</u>	<u>Good</u>	S.S. Lou No. 103-78	<u>11-82</u>	
Waterways		Breasthooks and Stenson			S.S. Lou No. 101-81		
Comings		Transoms, Pointers, and Crutches			Windlass and Capstan	<u>good</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings			Pumps	<u>2 Man 2 Blge</u>	
Lower Deck Beams & Fastenings		Ditto ditto at other places			Boats	<u>4</u>	
Planksheers		Keelsons			Masts, Yards, &c.		
Sheerstrakes		Clamps and Shelves			Condition, how ascertained	<u>from deck</u>	
Topsides		Ceiling			Sails	<u>2 suits</u> <u>good</u>	
Wales		Rudder	<u>buoled & painted</u>		Anchors, No. of	<u>3 B - 1 S - 2 K</u>	
Plank (Bottom) and Counter		Copper or Y.M. Cement When put on	<u>68</u>		Cables	<u>what seen</u> <u>good</u>	
Engine Room Skylights		Caulking of Bottom, Deck, & Waterways			Hawsers and Warps		
Coal Bunkers, Openings, Lids, &c.	<u>good</u>	Scuppers	<u>good</u>	Cargo and Main Hatchways	<u>good</u>	Hatches	<u>4</u>

General Observations, Opinion as to Class, &c.
This vessel was placed in dry dock, bottom examined scraped and painted, she appears in a sound & efficient condition, she appears eligible in my opinion to remain as classed.

Committee's Minute FRIDAY 5 OCT 1883
 Character assigned T.W. A.1.
 Edward John Tierney
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

(Form No. 3 for Annual Survey, when there are no repairs. 400-18/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Insert Character precisely as in Register Book.)

(Form No. 3 for Annual Survey, when there are no repairs. 400-18/5/83.)
 (If a Steam Ship, state if a Report is also sent on the Machinery...)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Insert Character precisely as in Register Book.)