14/8/83

ANNUAL SURVEYS.

43066

(Received at London Office, 16/8/83)

No. _____ Survey held at London Date, first Survey 11 July Last Survey 14 July & 21st 1883 (No. of Visits _____)

No. in Reg. Book. 161 on the SS New Pelton Master W B London

Tonnage: Net 525 Gross 821 Under Dk. 755 Built at Newcastle When built Year 1865 Month 4

By whom built Palmer Owners J Fenwick & Son

Port belonging to Newcastle Destined Voyage Coal Trade.

If Surveyed Afloat or in Dry Dock Pontoon Victoria Dk (State Name of Dock.) Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. 41663 Port of Sun

Classed — Years assigned: 80 A1 8.82; 55 M+ 81 — Character in Register Book. S.S. No. 3-78

Present Condition of the Decks: good
Waterways: "
Comings: "
Upper Deck Beams & Fastenings: "
Lower Deck Beams & Fastenings: "
Planksheers: "
Sheerstrakes: "
Topsides: "
Wales: "
Plank (Bottom) and Counter: "

Treenails: Rivets good
Breasthooks and Stemson: "
Transoms, Pointers, and Crutches: "
Timbers of the Frame at the Openings: "
Ditto ditto at other places: "
Keelsons: "
Clamps and Shelfs: "
Ceiling: "
Rudder: "
~~Copper or Y.M.~~ Boiler When put on new
Caulking of Bottom, Deck, & Waterways: good

Windlass and Capstan: good
Pumps: "
Boats: "
Masts, Yards, &c.: "
Condition, how ascertained: From Dk
Sails: good
Anchors, No. of 3 Bro. Sh & Hodges
Cables Part on Dk good
Hawsers and Warps: "
Standing and Running Rigging: "

Engine Room Skylights good Coal Bunkers, Openings, Lids, &c. good Scuppers good Cargo and Main Hatchways good Hatches "

General Observations, Opinion as to Class, &c. Bottom to be coated
She is now in an efficient state and eligible to remain as classed.

Senhouse Martindale

Committee's Minute TUESDAY 23 OCT 1883

Character assigned LBW 80 A

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18__

(Insert Character precisely as in Register Book.)

(The Surveyors are requested not to write on or below the space for Committee's Minute.) (If a Steam Ship, state if a Report is also sent on the Steam Ship, state if a Report is also sent on the Steam Ship, state if a Report is also sent on the

(Form No. 3 for Annual Surveys, where there are no repairs. 4000—18/5/83.)

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18__ (No. of Visits _____)

No. in Reg. Book. _____ on the _____ Master _____

Tonnage: Net _____ Gross _____ Under Dk. _____ Built at _____ When built Year _____ Month _____

By whom built _____ Owners _____

Port belonging to _____ Destined Voyage _____

If Surveyed Afloat or in Dry Dock _____ (State Name of Dock.) Society's Freeboard (if assigned) as painted on Ship _____

Last Survey, No. _____ Port of _____ Classed — Years assigned _____ Character in Register Book _____

Present Condition of the Decks
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter

Treenails
Breasthooks and Stemson
Transoms, Pointers, and Crutches
Timbers of the Frame at the Openings
Ditto ditto at other places
Keelsons
Clamps and Shelfs
Ceiling
Rudder
Copper or Y.M. _____ When put on _____
Caulking of Bottom, Deck, & Waterways

Windlass and Capstan
Pumps
Boats
Masts, Yards, &c.
Condition, how ascertained
Sails
Anchors, No. of
Cables
Hawsers and Warps
Standing and Running Rigging

Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____ Cargo and Main Hatchways _____ Hatches _____

General Observations, Opinion as to Class, &c.

Committee's Minute

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) _____ Paid _____ 18__

(Insert Character precisely as in Register Book.)

© 2021 Lloyd's Register Foundation

L0021-02748